


# testo 6383 Ethernet· differential pressure transmitter

## testo 6610 · Probes

# P2A software · Parameterizing, adjusting and analyzing software

Instruction manual Volume 1



# 1 Safety and the environment

### Avoiding electrical hazards

- Never use the instrument and connected probes to measure on or near live parts!
- > Damaged mains cables must only be replaced by authorized personnel.
- > Only have the transmitter wired and connected by authorized personnel with the voltage disconnected.
- You must always comply with the regulations applicable in your country for opening and repairing electrical equipment.

### Avoiding personal injury and damage to equipment

- > Installation, setting and calibration work must only be carried out by qualified and authorized personnel!
- Only open the instrument when this is expressly described in the instruction manual for installation, maintenance or repair purposes.
- > Observe the permissible storage, transport and operating temperature.
- > Do not store the product together with solvents. Do not use any desiccants.
- > Do not use the instrument for control purposes at the same time as operating or servicing the transmitter.
- Only operate the product properly, for its intended purpose and within the parameters specified in the technical data. Do not use any force.
- Carry out only the maintenance and repair work on this instrument that is described in the documentation. Follow the prescribed steps exactly. Use only original spare parts from Testo.

Any additional work must only be carried out by authorized personnel. Otherwise testo will not accept any responsibility for the proper functioning of the instrument after repair and for the validity of certifications.

### Protecting the environment

At the end of its useful life, send the product to the separate collection for electric and electronic devices (observe local regulations) or return the product to Testo for disposal.

# 2 About this document

#### Use

- > Please read this documentation through carefully and familiarize yourself with the product before putting it to use. Pay particular attention to the safety instructions and warning advice in order to prevent injuries and damage to the products.
- > Keep this document to hand so that you can refer to it when necessary.
- > Hand this documentation on to any subsequent users of the product.

<b>A</b> WARNING	Indicates potential serious injuries
<b>A</b> CAUTION	indicates potential minor injuries

### Symbols and writing standards

Representa- tion	Explanation
i	Note: Basic or further information.
1 2	Action: more steps, the sequence must be followed.
>	Action: a step or an optional step.
	Result of an action.
Menu	Elements of the program interface.
[OK]	Buttons of the program interface.
	Functions/paths within a menu.
" "	Example entries

# 3 Contents

1	Safe	ty an	d the environment	3
2	Abo	ut thi	is document	4
3	Con	tents		5
4	Tran	smit	ter	7
	4.1.	Spec	cifications	7
		4.1.1.	Functions and use	7
		4.1.2.	Scope of delivery	7
		4.1.3.	Accessories	7
		4.1.4.	Technical data	8
		4.1.5.	Dimensions	12
	4.2.	Prod	duct description	13
		4.2.1.	At a glance	13
		4.2.2.	Usable probes	14
		4.2.3.	Display and keypad	15
		4.2.4.	Service interface	15
		4.2.5.	Relay board (option)	
		4.2.6.	Analog outputs	
		4.2.7.	Parameters	
		4.2.8.	Scaling	
		4.2.9.	Alarm handling	19
	4.3.	Com	nmissioning	20
		4.3.1.	Mounting preparations	20
		4.3.2.	Connecting the instrument	21
			4.3.2.1. Overview of terminals	
			4.3.2.2. Connecting voltage supply and analog outputs	
			4.3.2.3. Connecting the relay outputs	
			4.3.2.4. Connecting pressure connections	
			4.3.2.5. Closing the instrument	
		4.3.3.	Ethernet communication	
			4.3.3.1. Types of operation	
			4.3.3.3. testo as a Saveris component	
			4.3.3.4. Integration into customer's Ethernet system	
			4.3.3.5. Adjusting the instrument	
			4.3.3.6. Overview: Adjustment keys and test contacts	

		4.3.3.7. 1-point adjustment (offset - humidity/temperature)	42
		4.3.3.8. 2-point adjustment (humidity/temperature)	44
		4.3.3.9. Analog output adjustment	44
		4.3.3.10. n-point adjustment (pressure)	46
		4.3.3.11. High-humidity adjustment for testo 6614	47
		4.3.3.12. Self adjustment of testo 6615 trace humidity probe	48
4.4.	Ope	ration	50
	4.4.1.	Relationship between user menu and mini-DIN socket is active	50
	4.4.2.	Password protection	50
	4.4.3.	Structure of user menu	50
	4.4.4.	Overview of the testo 6383 user menu	52
	4.4.5.	The individual main menus	55
		4.4.5.1. Editing main menu of channel 1	55
		4.4.5.2. Editing Main Menu Channel 2 (if this option is available)	55
		4.4.5.3. Editing Main Menu Channel 3 (if this option is available)	55
		4.4.5.4. Editing Main Menu Alarm	56
		4.4.5.5. Editing Main Menu Settings	57
		4.4.5.6. Editing Main Menu Analysis	60
		4.4.5.7. Editing Message main menu	62
		4.4.5.8. Calling up Main Menu Ident	63
		4.4.5.9. Editing Main Menu Adjust	63
		4.4.5.10. Editing Reset main menu	66
4.5.	State	us, warning and error messages	67
	4.5.1.	Status messages	67
	4.5.2.	Warning messages	69
	4.5.3.	Transmitter error messages	71
	4.5.4.	Handling alarm messages	72
	4.5.5.	Namur fault conditions	74
4.6.	Maiı	ntenance and cleaning	75
	4.6.1.	Maintaining the instrument	75
	462	Cleaning the instrument	75

# 4 Transmitter

# 4.1. Specifications

## 4.1.1. Functions and use

The testo 6383 transmitter is suitable for the following applications with Ethernet networking, amongst others:

- · Clean rooms
- Complex room climate applications

In addition to the signal transmission of the readings to a control unit via analog outputs, the measurement data can simultaneously be recorded, documented and visualized via Ethernet.

Furthermore, it is possible to issue an alarm for those responsible for the process, if necessary.

# 4.1.2. Scope of delivery

The scope of delivery of the testo 6383 transmitter includes the following:

- With KMAT version D04: Integrated humidity probe
- · Sealing frame
- Instruction manual
- Calibration report

# 4.1.3. Accessories

The following accessories are available for the testo 6383 transmitter, amongst others:

- Protection caps for probes
- Mains unit
- P2A software (parameterizing, adjusting and analyzing software)
- · Assembly accessories
- Information about accessories and their order numbers can be found in 8.2. volume 2, **Accessories and spare parts** or on the website at www.testo.com.

7

### 4.1.4. Technical data

#### **Parameters**

- Differential pressure
- Temperature
- Humidity

### Differential pressure accuracy



The specifications are only valid if the positive pressure is applied at the positive pressure connection.

- 0.3 % of measuring range, additional 0.3 Pa intrinsic error <sup>1</sup>
- T<sub>K slope drift</sub> = 0.02 % of measuring range per degree Kelvin of deviation from nominal temperature 22 °C
- T<sub>K zero point drift</sub>= 0 %, as zeroing with solenoid valve<sup>2</sup>

### **Humidity and temperature accuracy**

Depends on probe

### Humidity and temperature measuring range

· Depends on probe

# Pressure measuring range, resolution and overload of differential pressure

Pressure measuring range depending on version ordered	Resolution	Overload	
0 to 50 Pa	0.1 Pa	20,000 Pa	
0 to 50 Pa	0.1 Pa	20,000 Pa	

<sup>&</sup>lt;sup>1</sup> Measuring uncertainty in accordance with GUM: ±0.5 % of measuring range final value ±0.3 Pa. The determination of measurement uncertainty takes place according to GUM (Guide to the Expression of Uncertainty in Measurement):For the determination of measurement uncertainty, the accuracy of the measuring instrument (hysteresis, linearity, reproduceability), the uncertainty contribution of the test site as well as the uncertainty of the adjustment site (works calibration are taken into account. For this purpose, the value of k=2 of the extension factor, which is usual in measurement technology is used as a basis, which corresponds to a trust level of 95%.

 $<sup>^2</sup>$  Minor mixtures of the media may occur at the positive and negative pressure side due to the automatic zeroing cycle.

Pressure measuring range depending on version ordered	Resolution	Overload
0 to 100 Pa	0.1 Pa	20,000 Pa
0 to 500 Pa	0.1 Pa	20,000 Pa
0 to 10 hPa	0.01 hPa	200 hPa
-10 to 10 Pa	0.1 Pa	20,000 Pa
-50 to 50 Pa	0.1 Pa	20,000 Pa
-100 to 100 Pa	0.1 Pa	20,000 Pa
-500 to 500 Pa	0.1 Pa	20,000 Pa
-10 to 10 hPa	0.01 hPa	200 hPa



Upon delivery and following a factory reset the readings are shown in the display in the unit that was ordered via the KMAT option Fxx, .

## **Humidity and temperature resolution**

0.1 % RH or 0.01 °C/0.01 °F

## Meas. cycle

1/sec

#### Interface


- Mini-DIN for P2A software (parameterizing and adjusting software) and handheld testo 400/650
- Ethernet interface RJ45 (Ethernet 10 BatesT/100)

### Voltage supply

 4-wire (separate signal and supply lines): 20 to 30 V AC/DC, 300 mA power consumption

### **Maximum load**

4-wire: 500 Ω (power output)



#### **Maximal load**

4-wire: 10 kΩ (voltage output)

### **Analog output**

- 0 to 1 V ± 1.5 mV (4-wire) or
- 0 to 5 V ± 7.5 mV (4-wire) or
- 0 to 10 V ± 15 mV (4-wire) or
- 0 to 20 mA ± 0.03 mA (4-wire) or
- 4 to 20 mA ± 0.03 mA (4-wire)

### Resolution of analog output

• 12 bit

### Relay

4 relays, 250 V AC/DC, 3 A (optional)

### Display

• 2-line LCD with plain text line (optional)

### Operating temperature

-5 to 50 °C/23 to 122 °F

### Storage temperature

-20 to 60 °C/-4 to +140 °F

## Oper. humidity

0 to 90 % RH

### Housing, weight

- Metal/plastic
- Version with integrated humidity probe: approx. 1.35 kg
- Version with preparation for external humidity probe: approx.
   1.26 kg


### Protection class, frontal

 IP 65 only if the transmitter is wired, Ethernet connector is inserted and/or sealing plugs are inserted

### Directives, standards and tests


• EC Directive: 2014/30/EU

# 4.1.5. Dimensions




# 4.2. Product description

# 4.2.1. At a glance



- Sealing plugs on the positive pressure test connection (Ø 4 mm)
- 2 Sealing plugs on the negative pressure test connection (Ø 4 mm)
- 3 Socket for service plug
- 4 Display (optional)
- Keys (only with optional display)
- 6 Test rods for the analog outputs
- 7 Service cover screw connection (self-locking, 2 pcs.)
- 8 Aperture for front pressure connection
- 9 Openings for screws for fastening to the wall
- 10 Only with integrated humidity probe (KMAT option D04): Opening for the integrated humidity probe



- 11 9-pin connector for the current/voltage supply
- 12 Socket for Ethernet interface
- 13 Front pressure connection hose
- 14 Relay cover with 12-pin connector underneath for relay connection (option)
- 15 Negative pressure connection (Ø 6.4 mm )
- 16 Blind connection as hose holder for front pressure connection hose (Ø 6.4 mm)
- 17 Positive pressure connection (Ø 6.4 mm )
- 18 Probe socket

# 4.2.2. Usable probes

The testo 6383 transmitter can be used with the following probes:

Probes	Article no.	Characteristic
Integrated humidity probe	KMAT option D04 (0636 6610)	<b>Wall</b> probe version; accuracy to ±1 % RH; temperature range -20 to +70 °C/-4 to +158 °F, plug-on sensor
testo 6613	0555 6610-L13	Cable probe version; accuracy to ±1 % RH; temperature range -70 to +180 °C/ -94 to+356 °F, sensor soldered
testo 6614	0555 6610-L14	Heated cable probe version; accuracy to ±1.0 % RH; temperature range -40 to +180 °C/ -40 to +356 °F, sensor soldered

Probes	Article no.	Characteristic
testo 6615	0555 6610-L15	<b>Trace humidity cable</b> probe version; accuracy ±1 K at 0 °Ctd/+32 °Ftd; temperature range -40 to 120 °C/-40 to +248 °F, sensor soldered
testo 6617	0555 6610-L17	Cable with cover electrode monitoring probe version; accuracy to ± 1.2 % RH; temperature range -40 to 180 °C/ -40 to +356 °F, sensor soldered

# 4.2.3. Display and keypad

The display option allows operation of the testo 6383 transmitter via the display and four keys.

The LCD display consists of two 7-segment lines for displaying readings and units and of an information line (for status messages, for example).

The brightness and contrast of the display and the background lighting (permanent or off) can be changed via the user menu or the P2A software.

## 4.2.4. Service interface

The parameterizing socket (mini-DIN) is located behind the service flap as an interface to the P2A software or Testo handheld instrument (testo 400/testo 650).

# 4.2.5. Relay board (option)

This has a floating switch capacity of 250 V AC/3 A. The switching limits and hysteresis as well as the function as relay for the collective alarm can be set via the display or the P2A software.

Further features include:

- Function of changeover contacts (NC/NO contacts) freely selectable
- 12 terminals for a total of 4 relays.
- If no relays are available, settings for monitoring limit values or alarms can still be controlled via the display. The alarm status will be shown on the display.
- Only have the transmitter wired and connected by authorized personnel with the voltage disconnected.

# 4.2.6. Analog outputs

As analog outputs, the testo 6383 has either

- 1 or optionally 3 current outputs of 0 to 20 mA (4-wire)/4 to 20 mA (4-wire) or
- 1 or optionally 3 voltage outputs of 0 to 1 V/0 to 5 V/0 to 10 V (4-wire).


The transmitter can be ordered with three analog outputs as an option.

The optional three channels are galvanically isolated.

## 4.2.7. Parameters

The following parameters are displayed

- Differential pressure in Pa, hPa, kPa, mbar, bar, mmH<sub>2</sub>O, inch H<sub>2</sub>O, inch HG, kg/cm<sup>2</sup>, PSI
- Relative humidity in % RH (technical)
- Relative humidity in % WMO\* (calculation according to the WMO standard)
- · Degree of humidity in g/kg and gr/lb
- Absolute humidity in g/m³ and gr/ft³
- Water content in ppm (vol) and % vol
- Psychrometer temperature in °Ctw and °Ftw
- Enthalpy in kJ/kg and BTU/lb
- Water vapour partial pressure in hPa and inch H<sub>2</sub>O
- Dewpoint temperature in °Ctd and °Ftd
- Standardized dewpoint in °CtdA, standardized at atmospheric pressure (1013 hPa); precondition: Absolute process pressure.
- Dewpoint of H<sub>2</sub>O<sub>2</sub> mixture in °C<sub>tm</sub> and °F<sub>tm</sub>
- Mixture humidity H<sub>2</sub>O<sub>2</sub> in %RH<sub>m</sub>.
- \* It is possible that condensation appears as of a displayed humidity starting from 70 % and is shown on the display. This unit is used in meteorology, amongst others. When calculating the relative humidity the Magnus coefficient with undercooled water is used in accordance with WMO.



· Temperature °C and °F

# 4.2.8. Scaling

There are three types of min./max. values:

- 1 The measuring range: The maximum sensor performance is in this range. Values outside of the measuring range are displayed via messages, for example. Measuring range, see table (below).
- 2 Standard scaling: The output signals are assigned to this measuring range as standard:
  - during delivery if no entries are made in the order code
  - after exchanging the unit, the measuring range recorded in the instrument is applied as standard.
- The transmitter even retains its scaling with the voltage disconnected.

Measuring range, see table (below).

- 3 The maximum settings for the manual scaling
  - The maximum limits can be calculated as follows:
    - X = difference between MIN. and MAX. value of the standard scaling
    - (Max. value of standard) + (50 % of X)
    - (Min. value of standard) (50 % of X)
  - It is thus possible to scale beyond the measuring range, e.g. for the adjustment of the scaling limits to standard values of a PLC.

With the alarm definition, however, the physical measuring range limits are decisive.

Measuring range/standard scaling	Maximum scaling
0 to 50 Pa	-5 to 15 Pa
0 to 50 Pa	-25 to 75 Pa
0 to 100 Pa	-50 to 150 Pa
0 to 500 Pa	-250 to 750 Pa
0 to 10 hPa	-5 to 15 hPa
-10 to 10 Pa	-20 to 20 Pa
-50 to 50 Pa	-100 to 100 Pa
-100 to 100 Pa	-200 to 200 Pa
-500 to 500 Pa	-1000 to 1000
-10 to 10 hPa	-20 to 20 hPa

17

Parameter Unit		Probes	Physical measuring range at 1013 hPa		Standard scaling of transmitter measuring range	
			MIN	MAX	MIN	MAX
Temperature	°C	6611	-20	+70	-20	+70
	°F	6611	-4	+158	-4	+158
	°C	6613	-70	+180	-70	+180
	°F	6613	-94	+356	-94	+356
	°C	6614, 6617	-40	+180	-40	+180
	°F	6614, 6617	-40	+356	-40	+356
	°C	6615	-40	+120	-40	+120
	°F	6615	-40	+248	-40	+248
Dewpoint	$^{\circ}C_{td}$	6611	-20	+70	-80	+100
	°F <sub>td</sub>	6611	-4	+158	-112	+212
	$^{\circ}C_{td}$	6613, 6614, 6617	-20	+100	-80	+100
	°Ftd	6613, 6614, 6617	-4	+212	-112	+212
	$^{\circ}C_{td}$	6615	-60	+30	-80	+100
	°Ftd	6615	-76	+86	-112	+212
Absolute humidity	g/m³	all probes	0	600	0	2000
	gr/ft <sup>3</sup>	all probes	0	250	0	800
relative humidity <sup>3</sup>	% RH	all probes	0	100	0	100
WMO relative humidity <sup>3</sup>	% RH		0	100	0	100

-

 $<sup>^3</sup>$  For constant use in high humidity (> 80% rF at  $\leq$  30°C for > 12 h, > 60% rF at > 30°C for > 12 h), please contact us via www.testo.com/service-contact

Parameter	Unit	Probes	Physical measuring range at 1013 hPa		Standard scaling of transmitter measuring range	
Mixture humidity H <sub>2</sub> O <sub>2</sub>	% RH <sub>m</sub>		0	100	0	100
Mixture dewpoint	$^{\circ}C_{tm}$		-20	+100	-20	+100
$(H_2O_2)$	°Ftm		-4	+212	-4	+212
Degree of humidity	g/kg	all probes	0	13300	0	9500
	gr/lb	all probes	0	93000	0	66500
Enthalpy	kJ/kg		-40	99999	-40	8000
	BTU/lb		-18	43000	-18	3500
Psychrometer temperature	$^{\circ}C_{tw}$		-40	100	-40	180
	°Ftw		-58	210	-40	356
Water content	ppm (vol) H <sub>2</sub> O		0	99999	0	99999
	% vol		0	100	0	100
Water vapour	hPa		0	1000	0	7000
partial pressure	inchH <sub>2</sub> O		0	400	0	2800

## 4.2.9. Alarm handling

For upper and lower alarm limits, individual alarms as well as collective alarms can be specified. If the collective alarm function is activated, an alarm is triggered as soon as the alarm limit of an alarm is exceeded, if this alarm is assigned to the collective alarm.

The testo 6383 monitors limit values with the help of relays. If a reading is outside the limit values, a relay to be specified by the user is switched.


If the reading reverts to more than a specified hysteresis below or above the limit value, the alarm is cancelled.

In addition, information about the occurrence of error/status messages can be provided by means of a collective alarm relay, see 4.5. Status, warning and error messages.

If multiple alarm messages are activated at the same time, the last alarm is shown. If the alarm is cancelled again, the previous messages are no longer shown.

# 4.3. Commissioning

# 4.3.1. Mounting preparations



- Create a wall opening (approx. 120 mm x 220 mm) at the mounting location.
- 2. Hold 6383 in assembly position and mark the drill holes.
- 3. Drill holes suitable for the screws to be used.
- 4. Connect 6383.

# 4.3.2. Connecting the instrument



### **WARNING**


## Electrical voltage

### Danger of injury!

- > De-energize the mains connection before connecting the transmitter.
- i

Only have the transmitter wired and connected by authorized personnel with the voltage disconnected.


### 4.3.2.1. Overview of terminals



- 1 Terminal strip for voltage supply and analog outputs
- 2 Relay terminal strip (option), below the relay cover
- 3 Relay cover (option)
- 4 Insulating trough for relay board (option), below the relay cover


The following description of the terminals refer to this overview and its numbering.

## 4.3.2.2. Connecting voltage supply and analog outputs



Terminal strip for voltage supply and analog outputs, item (1) of overview of terminals

# Wiring diagram for 4-wire system (0 to 20 mA/4 to 20 mA/0 to 1 V/0 to 5 V/0 to 10 V)



- 1 1 or 3 channels, 0 to 20 mA/4 to 20 mA max. load per 500 Ω 0 to 1 V / 0 to 5 V / 0 to 10 V
- 2 Functional earth

i

Requirement for the connecting cable of the supply:

- Shielded and insulated with cross-section of at least 0.25 sq. mm, maximum 1.5 sq. mm without wire end sleeves.
- The supply line must be secured against exceeding 0.5 A.
- An OFF switch must be installed in an easily accessible position close by and be marked as such.
- 1. Disconnect terminal strip for voltage supply and analog outputs.

- 2. Strip the cable ends, clamp wire end ferrules on and screw down with voltage terminals/channel terminals.
- 3. Tie together each of the two adjacent cores using a cable tie.
- 4. Attach terminal strip for voltage supply and analog outputs.

## 4.3.2.3. Connecting the relay outputs

Only have the transmitter wired and connected by authorized personnel with the voltage disconnected.




Relay terminal strip, item (2) of overview of terminals

There is the option of twelve terminals for a total of four relays.

- 1. Remove relay cover.
- 2. Disconnect relay terminal strip.
- 3. Strip cable ends and clamp on wire end ferrules.
- Connect relays according to chosen function (NC/NO) (see diagrams below; relay 1 is shown as an example of a connection).


### **Connection note**



- For the connection, a double-insulated mains cable (sheathed cable) with a cross-section of at least 1.5 mm² must be used.
  - Cable connection (2) may not be routed in a loop within the relay trough (1).

- It is recommended that you always tie 2 adjacent cores to one another using a cable tie (3).
- The insulation of the cable must be fed at least 5 mm
   (4) into the relay tray up to the elevated part.


### Use of relay as NC contact (NC = normally closed)




- Alarm/status light (example of installation)
- 2 250 V AC/DC, 3 A

The busy light (alarm/status light) is permanently on until the relay opens or the circuit is interrupted. This circuit can therefore be used to monitor the functionality of the alarm circuit, as a cable break, for instance, is indicated by the busy light going off.

### Use of relay as NO contact (NO = normally open)



- The busy light (alarm/status light) only comes on when the relay is switched (closed). Monitoring the functionality of the alarm circuit is therefore not possible with this switching operation.
- 5. Insert relay terminal strip into socket.
- 6. Set on relay cover.




# 4.3.2.4. Connecting pressure connections

Illustration shows delivery status

### Use of front pressure connection


- Remove hose from hose holder (2) and connect to overpressure (3) or underpressure (1) connection.
- 2. Connect remaining pressure connection to (3) or underpressure potential (1) with additional hose.

## No use of front pressure connection




> Connect pressure potentials to (3) or negative pressure connection (1) on the rear via hoses.





- 1. Connect probe.
  - Version with integrated humidity probe:
  - 1. Insert probe into probe socket.
  - 2. Guide probe through opening of front plate.
  - 3. Tighten screw at opening.
  - Version with external humidity probe:
  - > Insert probe into probe socket.
- 4. Slide Ethernet connector into Ethernet socket.



- 5. Pull sealing frame (1) over the edge of the 6383.
- Screw on 6383. Initially, only tighten the screws slightly. When all screws are in position, also align 6383 and tighten the screws.
- 7. Seal 6383 using a measure appropriate for the installation point (e.g. with a silicone strip).

# 4.3.3. Ethernet communication

## 4.3.3.1. Types of operation

The type of operation can be set via the operating menu:

Settings | Ethernet | Mode |

- Saveris Probe Mode: a corresponding testo 6383 becomes a Saveris participant
- XML Server Mode: a corresponding testo 6383 can be integrated into unlimited Ethernet systems

### 4.3.3.2. Mains connection

Connect the network cable to the transmitter.

The network cable must not be connected directly to the telephone network (ISDN).

### 4.3.3.3. testo as a Saveris component

#### Set IP address

- √ Network cable must be connected to the Ethernet interface.
- Service plug must be connected.

The IP address of the transmitter can set be either via the P2A software (transmitter accessory) or via the configuration menu of testo Saveris<sup>TM</sup> (testo Saveris<sup>TM</sup> Ethernet Assistent).

- Set the IP address with the P2A software (see 7.3. volume 2, Using the software) or with the testo Saveris<sup>™</sup> Ethernet Assistent (see instruction manual).
- Remove service plug.

### **Using Saveris**

- Start Saveris software (see instruction manual measurement data monitoring with testo Saveris).
- Ensure that the Saveris software is not already open, for example in multi-user operation in Windows® Vista. If several clients are installed in one network, ensure that when clients are operating simultaneously, they do not carry out simultaneous alterations to the configuration of the system.
- 1. [Start] | All Programs | Testo |
- Select Saveris Professional Client (full version). The selection is available if Saveris Professional Client is installed.
- Select Saveris Viewer (restricted functionality). The selection is available if the Saveris Viewer is installed.
- The program window Testo Saveris software is opened with the dialog Select project.



Should the Software not start, check in the service s administration of the operating system whether the service testo tdassvcs is started, and if necessary, restart.

### 2. The option

- Select Only active projects when the data of a current project are to be opened.
- Select All projects when the data of a closed project are to be opened.
- 3. Select the project to be opened from the tree structure.
- 4. Confirm with [OK].
- The program window Testo Saveris software is displayed in the foreground with the selected data set.

## 4.3.3.4. Integration into customer's Ethernet system

#### Precondition

i

The user should be familiar with the structure of an XML document. Furthermore, enough knowledge should be available that this type of document can be downloaded and decoded via an Internet connection with the aid of a programming/script language.

#### Interface

The communication takes place according to the client/server principle, whereby the Ethernet module takes on the role of the server:

The XML interface will be approached via a URL. The URL consists of the IP address of the Ethernet module, the path for the XML document and, depending on the URL, with a clearly defined

parameter. If a parameter is missing or an incorrect value is transferred, the Ethernet module sends back a simple error message.

Example:

IP address = 254.169.100.100

URL for serialnumber.xml:

http://254.169.100.100/data/getserialnumber

If a parameter is required, a "?" is always in the first place after the URL, then the parameter is transferred to the common guery string form (name=value).

Example:

IP address = 254.169.100.100

URL for / identification.xml:

http://254.169.100.100/data/getidentification?param=0 (compare table xml codes)

After calling up the compound URL, if everything was correct, an XML document is returned. With faulty parameters a simple HTML answer comes that points out the reason that an XML answer could not be given.

If an XML document is to be loaded on the server, access is provided by means of a POST request

Example of an upload via the program wget:

IP address = 254.169.100.100

URL for / usersettings.xml:

Path details of the folder in which the wget program is located

Command

Path details of the folder in which the usersettings XML file is the next page)

IP address of the transmitter and required URL (see table on

H:/wget/wget-complete-stable

/wget --post-file=

C:/usersettings.xml

located

254.169.100.100/config/ setusersettings

The Ethernet module supports reading out of

- Readings
- Instrument type (testo 6383)
- Firmware date and version (testo 6383)
- Status and status messages (testo 6383)
- Alarm messages (testo 6383)
- Service hour counter (testo 6383 and probe)

as well as the reading and writing of the:

- Adjustment data (testo 6383)
- Configuration data of analog outputs (testo 6383)
- Configuration data of relays (testo 6383)
- User settings (testo 6383)

## XML codes (download)

The table of xml-codes is available for download www.testo.com/download-center (requires registration).

URL	Description	Parameter	Answer (see Appendix)
/data/getserialnumber	Read off serial number of connected transmitter		serialnumber.xml
/data/getidentification	Read off type of connected transmitter/ probe	param=0 (for transmitter) param=1 (for probe)	identification.xml
/data/getversion	Read off firmware version of connected transmitter		version.xml
/data/getfirmwaredate	Read off firmware date of connected transmitter		firmwaredate.xml
/data/getonlinevalue	Read off online values of connected transmitter		onlinevalue.xml
/data/getviewchannels	Read off view channels of connected transmitter		viewchannels.xml
/data/getstatus	Read off status of connected transmitter		status.xml
/data/getlaststatusmessa ge	Read off last status message of connected transmitter		laststatusmessage.xml
/config/gethourscount	Read off service hour counter of transmitter or probe		hourscount.xml
/config/getusersettings	Read off settings of transmitter		usersettings.xml
/config/getcalibration	Read off adjustment data of transmitter	param=0 (adjustment set 1) param=1 (adjustment set 2) param=2 (adjustment set 3)	ound autom same
/config/getreldefinition	Read off relay information of transmitter	param=0 (relay 1) param=1 (relay 2) param=2 (relay 3) param=3 (relay 4)	reldefinition.xml
/config/getheatertime	Read off sensor heating information		heatertime.xml
/config/getoptions	Read off options of transmitter		options.xml
/config/getcollectivealarm	Read off alarm messages of transmitter		collectivealarm.xml

## **Upload XML documents**

URL	Description	Parameter	Post	Answer (see Appendix)
/config/setusersettings	Perform settings of transmitter		usersettings.xml	usersettings.xml
/config/setcalibration	Set adjustment data of transmitter	param=0 (adjustment set 1) param=1 (adjustment set 2) param=2 (adjustment	calibration.xml	calibration.xml
/config/setreldefinition	Set relay information	set 3) param=0 (relay 1)	reldefinition.xml	reldefinition xml
- Tooling out old olimited in	of transmitter	param=1 (relay 2) param=2 (relay 3) param=3 (relay 4)	Toldoninition.xiiii	Total million.xm
/config/setheatertime	Set sensor heating information		heatertime.xml	heatertime.xml
/config/setoptions	Set options of transmitter		options.xml	options.xml
/action/setresettm	Not yet implemented		resettm.xml	

## **Description of the XML elements**

### General elements

XML tag	Description	Туре
measurement_value	Parent element. Contains the child elements value, unit, resolution	
value	Reading	Numerical, decimal number
unit	Unit	ASCII
number_values	Qty.	Numerical, whole number

### Elements in calibration.xml

XML tag	Description	Туре
calibration_data	Base element. Contains the child elements unit, attenuation, cal_reserved, cal_offset, cal_scale.	
unit	See general elements	
attenuation	Damping (0 - 15)	Numerical, decimal number
cal_offset	Offset	Numerical, whole number

XML tag	Description	Туре
cal_scale	Parent element. Contains the child elements cal_minscale, cal_maxscale	
cal_minscale	Scaling value	Numerical, decimal number
cal_maxscale	Scaling value	Numerical, decimal number

### Elements in collectivealarm.xml

XML tag	Description	Туре
colalarmtable	Base element. Contains the child elements alarm_numbers, alarm	
alarm_numbers	Number of alarm messages	Numerical, whole number
alarm	Parent element. Contains the child elements alarm_event, alarm_state	
alarm_event	Type of alarm	ASCII
alarm_state	Status of the alarm 0 = alarm inactive	Numerical, whole number
	1 = alarm active	

## Elements in firmwaredate.xml

XML tag	Description	Туре
firmware_date	Base element. Contains the child elements year, month, day	
year	Year	Numerical, whole number
month	Month	Numerical, whole number
day	Day	Numerical, whole number

### Elements in heatertime.xml

XML tag	Description	Туре
heatertime	Base element. Contains the child element heatertimeoff	
heatertimeoff	Time sensor heating off in min	Numerical, whole number

### Elements in hourscount.xml

XML tag	Description	Туре
hourcount	Base element. Contains the child element hours	
hours	Service hour counter in h	Numerical, whole number

### Elements in identification.xml

XML tag	Description	Туре
	Base element. Contains the child element device_id	
device_id	Transmitter type	Numerical, whole number

### Elements in laststatusmessage.xml

XML tag	Description	Туре
mufmsg	Base element. Contains the child elements msg, sn, hours	
msg	Status message	ASCII
sn	Serial number	ASCII, 8 characters
hours	Service hour counter in h	Numerical, whole number

### Elements in onlinevalue.xml

XML tag	Description	Туре
online_values	Base element. Contains the child elements number_values, measurement_value	
number_values	See general elements	
measurement_value	See general elements	

## Elements in options.xml

XML tag	Description	Туре
options	Base element. Contains the child elements device_options, production_options	
device_options	See device_options description	Numerical, whole number
production_options	See production_options description	Numerical, whole number

### Elements in reldefinition.xml

XML tag	Description	Туре
relay_data	Base element. Contains the child elements relay_channel, relay_number, relay_status, sw_point_character, sw_point_value, hysteresis_value	
relay_channel	Measurement channel linked to the relay	Numerical, whole number
relay_number	Relay number (0 - 2)	Numerical, whole number

# 4 Transmitter

XML tag	Description	Туре
relay_status	Status of relay 0 = off	Numerical, whole number
	1 = on	
sw_point_charact	Switch point: Switch point: 0 = low-limit monitoring	Numerical, whole number
	1 = high-limit monitoring	
sw_point_value	Switch point	Numerical, decimal number
hysteresis_value	Hysteresis	Numerical, decimal number

## Elements in serialnumber.xml

XML tag	Description	Туре
serialnumber	Base element. Contains the child element number	
number	Serial number	ASCII, 8 characters

## Elements in status.xml

XML tag	Description	Туре
mufstatus	Base element. Contains the child elements statemsg, staterel, statecounter	
statemsg	Status message	Numerical, whole number
	See statemsg description	
staterel	Status relay	Numerical, whole number
	See staterel description	
statecounter	Counter	Numerical, whole number

## Elements in usersettings.xml

XML tag	Description	Type
usersettings	Base element. Contains the child elements (pressure)*, (abs_pressure_pa_process)*, (humidity_process)*, (temperature_c_process)*, (humidity_norm)*, (abs_pressure_pa)* h2o2, setting_display, backlight, contrast, language, disp_msg, h2o2_prozess	,
pressure	Absolute pressure	Numerical, decimal number
h2o2	H2O2 value	Numerical, decimal number
setting_display	Auto OFF background lighting 0 -> background lighting auto off 1 -> background lighting stays on	Numerical, whole number
backlight	Brightness of background lighting 0 to 9 (0 = off, 9 = max.)	Numerical, whole number
contrast	Display contrast 0 to 9 (0 = min., 9 = max.)	Numerical, whole number
language	Language 0 ->GERMAN 1 ->ENGLISH 2 ->FRENCH 3 ->SPANISH 4 ->ITALIAN 5 ->JAPANESE 6 ->SWEDISH	Numerical, whole number
disp_msg	Status messages display 0 = off 1 = on	Numerical, whole number
h2o2_prozess	H2O2 process 0 = via H2O2 water 1 = process with evaporated H2O2	Numerical, whole number
abs_pressure_pa_process,	Pressure process data, absolute pressure in Pa	Numerical, decimal number
humidity_process	Pressure process data, process humidity in % RH	Numerical, decimal number
temperature_c_process	Pressure process data, process temperature in °C	Numerical, decimal number

st Child elements are optional

XML tag	Description	Туре
abo_pressure_pa	Humidity process data, absolute pressure in Pa	Numerical, decimal number

#### Elements in versions.xml

XML tag	Description	Туре
firmware_version	Base element. Contains the child element version	
version	Firmware version:	ASCII, 6 characters

#### Elements in viewchannels.xml

XML tag	Description	Туре
view_channels	Base element. Contains the child elements number_values, view_channel	
number_values	See general elements	
view_channel	Parent element. Contains the child elements channel_info, measurement_value, meas_status	
channel_info	Parent element. Contains the child elements connector_info, channel_type	
measurement_value	See general elements	
meas_status	Parent element. Contains the child elements min, max, mean	
connector_info	Channel (transmitter/probe)	ASCII
channel_type	Parameter details	ASCII
min.	Minimum reading	Numerical, decimal number
max.	Maximum reading	Numerical, decimal number
mean	Mean value	Numerical, decimal number

#### production\_options description

Content of production\_options is a double word type number (32 bit). The individual hardware options are bit-coded here.

xxxx xxxx xxxx xxxx xxxx xxx1 2222 3334

- 1 0=2-wire 1=4-wire
- 2 free

#### xxxx xxxx xxxx xxxx xxxx xxx1 2222 3334

3 0=4 to 20 mA

1=0 to 20 mA

2=0 to 1 V

3=0 to 5 V

4=0 to 10 V

4 0=1 analog output

1=3 analog outputs

#### device\_options description

Content of device\_options is a double word type number (32 bit). The individual instrument options are bit-coded here.

#### XXXX XXXX XXXX XXXX XXXX 1222 2345

- 1 0=probe is invalid 1=probe is valid
- 2 free
- 3 free
- 4 0=no relay present 1=relay present
- 5 0=no display 1=display present

#### statemsg description

Content of statemsg is a double word type number (32 bit). The individual status messages are bit-coded here.

If statemsg = 0 there are no new messages.

If statemsg != 0

#### XXXX XXXX XXXX XXXX XXXX 1234 5678

- 1 free
- 2 1=probe information
- 3 1= probe warning
- 4 1=probe error
- 5 free
- 6 1=transmitter information
- 7 1=transmitter warning
- 8 1=transmitter error

#### staterel description

Content of staterel is a double word type number (32 bit). The individual relay states are bit-coded here.

XXXX XXXX XXXX XXXX XXXX XXXX 1234


- 1 0=relay 4 is not set 1=relay 4 is set
- 2 0= relay 3 is not set 1=relay 3 is set
- 3 0=relay 2 is not set 1=relay 2 is set
- 4 0=relay 1 is not set 1=relay 1 is set

More information can be found in the download area at www.testo.com.

#### 4.3.3.5. Adjusting the instrument

The testo adjusting concept allows the entire signal chain from the sensor signal (probe) and the digital signal (within the transmitter) through to the analog signal (transmitter output signal) to be adjusted (see diagram).

1-point adjustment	2-point adjustment
Adjustment via     testo 400/650     handheld instrument     with adjustment     adapter     P2A software     User menu	Adjustment 11.3 % RH/ 75.3 % RH and 20 % RH/ 80 % RH via • User menu • P2A software
Analog adjustment	n-point adjustment



Adjustment using a precise multimeter and transmission of analog reference value in


precise pressure sensor and transmission of analog reference value in

- · User menu or
- P2A software
- User menu orP2A software

Either the 1-point adjustment or 2-point adjustment is suitable for adjusting the sensor signal - digital signal chain.

The testo 6383 transmitter has digital probes whose adjustment information is stored in the probes' internal memory. Both 1-point and 2-point adjustments can thus be carried out on another testo 6383 (e.g. in the calibration laboratory).


#### 4.3.3.6. Overview: Adjustment keys and test contacts



- 1 Contact ch. 1
- 2. Contact ch. 2
- 3. Contact ch. 3
- 4. Service interface

#### 4.3.3.7. 1-point adjustment (offset - humidity/temperature)

In the 1-point adjustment, the reading at the working point is raised to the reference value so that there is no longer any deviation in the working point. The reference condition can be measured using a precise handheld instrument (e.g. testo 400/650 with precision humidity probe) or be created in an air conditioning cabinet.



- Deviation
- 2 Working point
- 3 Working range

The advantage of the 1-point adjustment is the good measuring result in the working range. But the further away the measurement is from the working point, the greater the deviation can become. The 1-point adjustment should therefore only be used for a relatively narrow measuring range (working range), e.g. clean room applications, air conditioning applications for storage and similar.


The 1-point adjustment can be performed

- via the user menu see 4.4.5.9. Editing Main Menu Adjust or
- via the P2A software (see 7.3.4.1. Band 2, 1-point adjustment)
- directly by means of a Testo handheld instrument (testo 400/650) (see description of how to proceed below).

Please note that the 1-point adjustment is generally performed on the basis of the % RH and °C/°F parameters.

#### Adjusting testo 6383 using testo handheld instrument

√ The service flap is open, a testo 400/650 handheld instrument with a precision humidity probe is ready.




- Connect testo handheld instrument 400/650 (1) with connected humidity reference probe (3) (order no. reference set 0699 3656/20) to the service interface (5) of the testo <v>T -Produktname MUF</v> via the adjustment adapter (2) (connected to probe socket 1 of the handheld instrument).
- Expose the humidity probe (4) of the testo <v>T Produktname MUF</v> and the reference probe (3) to the same reference conditions (e.g. in the humidity generator) and allow climatic conditions to equalize.
- 3. Switch on the testo 400/650. The two-part display of the handheld instrument will show the values of the transmitter on the left, and the values of the reference probe on the right. The humidity and temperature values are adjusted to the reference probe using the Probe > Probe Adjustment menu item on the testo 400/650. The 1-point adjustment is performed for both the humidity and the temperature.
- 4. Disconnect the adjustment adapter (2) from the service interface (5).
- 5. Close the service flap.
- Adjustment with the standard testo adjustment salt pots is not suitable for the testo 6614 (heated for high-humidity applications) and testo 6615 (trace humidity) probes.

  The reference conditions should be generated in a humidity generator to adjust these probes. In addition, these probes can also be adjusted at a third adjustment point by Testo Service.
  - testo 6614: third adjustment point at 90 % RH
  - testo 6615: third adjustment point at -40 °Ctd/-40 °Ftd

#### 4.3.3.8. 2-point adjustment (humidity/temperature)

With the 2-point adjustment, the parameter is adjusted to the reference value at the two standard adjustment points 11.3 % RH and 75.3 % RH or 20 % RH and 80 % RH. The reference conditions are created either by using testo adjustment salt pots (order no. 0554 0660, only for adjustment points 20 %RH and 80 %RH) or in the humidity generator.



In the 2-point adjustment, the deviations between the reading and the nominal value are minimized across the entire measuring range. The 2-point adjustment is therefore recommended for large working ranges.

The 2-point adjustment can be performed


- via P2A software (only for the adjustment points 11.3 %RH and 75.3 %RH) or
- via the operating menu.



A previous 1-point adjustment is undone during a 2-point adjustment.

#### 4.3.3.9. Analog output adjustment

The purpose of adjusting the analog outputs is to adjust the signal chain from the digital signal (within the transmitter) to the analog outputs. The signal type that was appointed for the transmitter is adjusted respectively for each channel (e.g. 4 to 20 mA or 0 to 1 V, etc.).



- Contact ch. 1
- 2. Contact ch. 2
- 3. Contact ch. 3
- 4. Service interface


#### Adjusting analog outputs 1, 2 and 3 (optional)

- $\checkmark$  With testo 6383 with current output: Load of max. 500  $\Omega$  is connected to channel that is to be adjusted see 4.3.2.2. Connecting voltage supply and analog outputs.
- √ A precise multimeter (minimum requirement: resolution 6.5 digits, at least 5-times more accurate than the 6383) is available.
- If only a simple multimeter is available, the analog outputs must not be adjusted.
- ✓ The service cover is open.
- 1. Connect the inputs of the multimeter with the contacts (1) and (2) for channel 1 or with contacts (3) and (4) for channel 2, (5) and (6) for channel 3.

- Transfer the reference analog value measured with the multimeter into the P2A software (see 7.3.4.4. volume 2, Adjusting the analog output) or enter it via the user menu (see 4.4.5.9. Editing Main Menu Adjust).
- 3. Disconnect connections between the multimeter and the contacts of the testo 6383 and close the service cover.


#### 4.3.3.10. n-point adjustment (pressure)

With an n-point adjustment, the parameters at the 3-6 measurement points are adjusted to the reference value. The reference conditions are obtained by using a precise pressure sensor that should be 5-times more accurate than the transmitter.



- 1 Positive pressure connection
- 2. Negative pressure connection
- 3. Pressure sensor

- The number of measuring points is set to 3 by the factory and can only be changed using the P2A software (see 7.3.4.3. **n-point adjustment**).
- The n-point adjustment must always be carried out to its full extent and in good time at all selected measurement points.
- A precise pressure sensor (5-times more accurate than the transmitter, e.g. DPC precision pressure sensor from testo industrial services) is available.
- 1. Connect the positive output of the pressure sensor (3) to the positive pressure connection of the transmitter (1) and the negative output of the pressure sensor (3) to the negative pressure connection of the transmitter (2).
- Transfer the reference pressure value created with the pressure sensor into the P2A software (see 7.3.4.3. volume 2, n-point adjustment) or enter it via the user menu (see 4.4.5.9. Editing Main Menu Adjust).
- 3. Repeat step 2 for all of the measuring points.
- 4. Disconnect connections between the pressure sensor and the pressure connections of the testo 6383.



#### 4.3.3.11. High-humidity adjustment for testo 6614

With the testo 6614, the rear of the Testo humidity sensor is heated, creating a microclimate around the sensor (within the filter) that is constantly 5 K warmer than the actual process conditions. As can be seen in the Mollier diagram, this reduces the relative humidity at the sensor from around 100 % RH to a lower value, e.g. 73 % RH. In this range, the reaction time of the sensor is noticeably shorter than in the condensation range and the risk of the sensor corroding is also reduced. Using the separate temperature probe, the testo 6383 transmitter compensates the microclimate conditions and displays the process readings.


The reference conditions (11.3 % RH and 75.3 % RH or 20 %RH and 80 %RH) for the 2-point adjustment of the testo 6614 should be generated in a humidity generator, as humidity adjustment sets cannot be used due to the heat generated.

The adjustment can also be carried out at a third adjustment point (90 % RH) by Testo Service so that optimum accuracy is also achieved in the high humidity ranges.

#### 4.3.3.12. Self adjustment of testo 6615 trace humidity probe

Conventional trace humidity probes show a steep rise in measuring uncertainty at low humidities. In the testo 6615 trace humidity probe, these measuring uncertainties are corrected by means of an automatic self-adjustment process. This means that extremely accurate measuring results are also attained to -60 °Ctd.

To this end, a temperature sensor is fitted on the back of the testo 6615 which is used as a heater. A humidity and temperature value pair is taken in both the unheated and heated state. The deviation of the probe obtained from these pairs of values is automatically corrected.



The graph shows the effect of the self-adjustment, e.g. during the Init. phase.


- 1 Self-adjustment
- 2 Correction of measurement value
- 3 Process dew point temperature

For the effectiveness of the self-adjustment the following prerequisites are decisive over the duration of the self-adjustment.

- The process temperature should not vary by more than 0.5K
- The dew point temperature should remain stable, as far as possible
- · The process pressure should not vary excessively
- i

If these prerequisites cannot be fulfilled, the values obtained during the last successful self-adjustment will be maintained.

All adjustment processes are saved in the history of the transmitter, see 7.3.5. **Transmitter history**.



- i
- Deactivating the adjustment function of the testo 6615 will reduce measuring accuracy and should therefore be restricted to the shortest possible length of time.
- During the heating phase, the relay and analog outputs, the display value and output value are "frozen", see diagram above. Self-adjustment active is shown in the display until it has finished. The factory setting for selfadjustment time (incl. heating time, calculation time, cooling time) requires 30 minutes daily. The cycle time can be edited via the operating menu or the P2A software.
- In the factory setting, a third adjustment point (-40 °C<sub>td</sub>) is approached for the testo 6615 in addition to the 2-point adjustment. This special adjustment can be performed again by your Testo Service team if necessary.

# 4.4. Operation

# 4.4.1. Relationship between user menu and mini-DIN socket is active

The testo 6383 can be parameterized using either the user menu or the P2A software (see 7. volume 2, Parameterizing, adjusting and analyzing software (P2A software)).



The testo 6383 transmitter can only be operated via the display and keypad if the display option is available.

If the testo 6383 is connected to the P2A software, the user menu is blocked for the duration of the communication. The message Service plug is shown in the display of the testo 6383. As soon as the P2A software is disconnected, the user menu is accessible again.

## 4.4.2. Password protection

The user menu can be protected with a four-digit numerical code (see 4.4.5.5. Editing Main Menu Settings) so that access to the user menu is denied to unauthorized persons not familiar with this numerical code.

If the password protection is not to be used, the numerical code "0000" must be entered. This is also the status upon delivery.

#### 4.4.3. Structure of user menu

At the main menu level, the user menu comprises the following:

- Main Menu Channel 1
- Main menu of channel 2 (if this option is available)
- Main menu of channel 3 (if this option is available)
- Main Menu Alarm
- Main Menu Settings
- Main Menu Analysis
- Main Menu Messages
- Main Menu Ident
- Main Menu Adjust
- Main Menu Reset





- 1 Channel 1 display
- 2 Channel 2 display
- 3 Channel 3 display or for messages


Four keys enable the user to navigate/scroll through the menus and enter/amend values and settings:

Key	Function/description
SET	<ul> <li>In Measuring Mode: changes to parameterization</li> <li>In Parameterizing Mode: confirms a selection or setting</li> </ul>
ESC	Leaves a menu (without modifying any settings)
<b>&gt;</b>	<ul> <li>Selecting: scrolls through menus (downwards) or selectable alternatives</li> <li>Editing: changes to next digit (to the right)</li> </ul>
•	Selecting: scrolls through menus (upwards) or selectable alternatives     Editing: increases the value of the current digit by 1

### 4.4.4. Overview of the testo 6383 user menu







#### 4.4.5. The individual main menus

#### 4.4.5.1. Editing main menu of channel 1

An overview is given in 4.4.4. Overview of the testo 6383 user menu).

You can perform basic settings for channel 1.

 In the Measuring Mode press SET, select Main Menu Channel 1 with ▶ or ▲ and confirm selection with SET.

One of the following parameters can now be selected using **>** or **\( \Lambda \)**, after which the selection must be confirmed with **SET**:

Channel 1 Unit

The parameter for this channel is selected.

Edit/select parameter with ▶ or ▲, confirm with SET or abort entry with ESC.

Scale minimum for channel 1:

The lower scale limit is edited; Unit as selected above.

Editing the value: Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.

Scale maximum for channel 1

The upper scale limit is edited;

Unit as selected above.

Editing the value: Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.

Signal delay ("Attenuation") for channel 1

The analog signal can be delayed ("Attenuation"); a time constant is selected for this (1 = no delay; 2-15 = delay in seconds)

Edit/select parameter with ▶ or ▲, confirm with SET or abort entry with ESC.

 Continue to the main menu with ▶ or ▲ or return to Measuring Mode with ESC.

# 4.4.5.2. Editing Main Menu Channel 2 (if this option is available) See channel 1.

# 4.4.5.3. Editing Main Menu Channel 3 (if this option is available) See channel 1.

#### 4.4.5.4. Editing Main Menu Alarm

With the alarm, the relays, available as options, are programmed. In addition, the alarm statuses are shown on the display (top right) (even without relays).

You can choose whether the alarm is to be used to monitor limit values or as a collective alarm. If an alarm is to be used to monitor limit values, you can choose between monitoring the minimum or maximum value and set a limit value and hysteresis for each alarm.

In addition, every alarm can be linked to a clearly visible visual alarm (display background lighting and the corresponding measurement value flash when limit values are violated).

An alarm delay between 0 and 3600 seconds can still be assigned to every alarm used for limit value monitoring so that both the corresponding relay effect and the visual alarm are delayed. If the alarm status goes out within the set alarm delay time, neither the visual alarm nor a relay connection is triggered.

With an alarm status present, the visual alarm and all relay outputs can be reset by means of acknowledgement with any button. The triggering of a new alarm cannot be enabled until after the alarm status goes out.

- In the Measuring Mode press SET, select Main Menu Alarm with ▶ or ▲ and confirm selection with SET.
- Four alarms can be parameterized.
- 2. Select Alarm x with ▶ or ▲ and confirm selection with SET.

#### Using alarm to monitor limit values

#### **NO** contact

Monitoring minimum

Hysteresis

On


Off

Limit value

# Monitoring maximum Hysteresis On Off

#### NC contact

Monitoring minimum



#### Monitoring maximum Hysteresis



Limit value

- Select Channel x (e.g. "Channel 1") with ▶ or ▲ and confirm selection with SET.
- Select Max control or Min control with ▶ or ▲ (see graphic).
- Press SET and edit Limit value as well as Hysteresis: Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.
- Select Visual alarm with ▶ or ▲. Select YES or NO with ▶ or ▲. Confirm with SET or abort entry with ESC.
- Press SET and edit Alarm delay: Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲ (0 to 3600 seconds possible). Confirm with SET or abort entry with ESC.
- 8. Return to Channel x with ESC.
- 9. Return to Alarm x with ESC.
- 10. Change to the other relays using ▶ or ▲ and perform settings in the same way.

#### Using alarm as collective alarm or not using it at all

If an alarm is assigned to the collective alarm, the relay is switched and a visual alarm can be issued via the display as soon as (at least) one of the warning or error messages of the testo 6383 transmitter (or the connected testo 6610 probe) becomes active.

- The messages affecting the collective alarm can only be selected in the P2A software, see 7.3. volume 2, Using the software.
- ✓ Alarm is selected (see previous steps 1 and 2).
- Use ➤ or ▲ to determine whether Alarm x should be used as a Collective alarm or not used. Confirm selection with SET.
- If collective alarm is selected: Select Visual alarm with ▶ or ▲. Select YES or NO with ▶ or ▲. Confirm with SET and return to Alarm x.
- Change to another alarm using ▶ or ▲ and perform settings in the same way.
- 4. Return to Main Menu Alarm with ESC.
- Continue to Main Menu Settings with ▶ or ▲ or return to Measuring Mode with ESC.

## 4.4.5.5. Editing Main Menu Settings

You can edit instrument settings and other settings.

> In Measuring Mode, press SET, select Main Menu Settings using ▶ or ▲ and confirm selection with SET. You can edit settings for:

- Display
- Language
- Code
- Units
  - Absolute pressure
  - Area
  - Temperature
- Humidity process data
  - H2O2 percentage by weight
  - Humidity process pressure

#### **Editing display settings**

You can set the brightness and contrast of the display.

- Select Display Settings with ▶ or ▲ and confirm selection with SET.
- Select Backlight or Contrast with ▶ or ▲ and confirm selection with SET.

One of the following parameters can now be selected using ▶ or ▲, after which the selection must be confirmed with SET:

Backlight

The display illumination is changed.

Edit/select parameter with ▶ or ▲, confirm with SET or cancel entry with ESC (the effect of the change in parameter can be seen during input).

Contrast

The brightness difference between the display background and the displayed values is changed.

Edit/select parameter with ▶ or ▲, confirm with SET or cancel entry with ESC (the effect of the change in parameter can be seen during input).

Backlight 24h on

Select On or Off using ▶ or ▲ and confirm with SET.

Off: The display light switches off automatically if no button was pressed for 10 seconds.

On: The display light is activated

Return to Display Settings with ESC and use ➤ or ▲ to continue to Language.

#### Selecting language

You can select the language for the plain text line in the display.

- > Press SET, select required language with ▶ or ▲, confirm selection with SET and return to Language.
- Only choose a language that you can understand well.

#### **Editing code settings**

You can set the access code (password).

- If a code other than "0000" (factory setting) is set, the transmitter can only be operated once this code has been entered via the menu.
- 1. Select Code with ▶ or ▲ and confirm selection with SET.
- Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.
- Return to Code with ESC and use ► or ▲ to continue to Change parameters.

#### Select unit (Change unit)

This setting affects the displayed unit of all readings.

- Press SET, select Change parameters with ▶ or ▲, confirm selection with SET or cancel with ESC.
- Select Change unit with ▶ or ▲, confirm selection with SET or cancel with ESC.
- Select the required variable (absolute pressure/area/temperature) with ▶ or ▲, confirm selection with SET or cancel with ESC.
- Select the required unit with ▶ or ▲, confirm selection with SET or cancel with ESC.
- 5 Return to Change unit with ESC.
- 6. Return to Change parameters with ESC.
- Return to Main Menu Settings with ESC.

#### **Editing Humidity process data**

This menu is only used to parameterize humidity measurements in  $H_2O_2$  atmospheres (e.g. in sterilization processes) and determines whether °Ctm or °Ftm is the output parameter.

- Select Humidity process data with ▶ or ▲ and confirm selection with SET.
- Select H202 weight prop. with ▶ or ▲, confirm selection with SET or cancel with ESC.

The selection  $H_2O_2$  passively vaporized or  $H_2O_2$  actively vaporized in the submenu describes whether  $H_2O_2$  is generated by means of evaporation or is actively vaporized in the process.

- Select H<sub>2</sub>O<sub>2</sub> passively vaporized or H<sub>2</sub>O<sub>2</sub> actively vaporized with ▶ or ▲ and confirm with SET.
- Edit proportion by weight of the H<sub>2</sub>O<sub>2</sub> in % (% H<sub>2</sub>O<sub>2</sub> proportion by weight in the liquid initial solution): Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.
- Return to H202 weight prop. with ESC and use ➤ or ▲ to continue to Humidity process pressure.
- Select Humidity process pressure with ▶ or ▲ and confirm selection with SET.
- Edit humidity process pressure: Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.
- 8. Return to Change parameters with ESC.
- Return to Main Menu Settings with ESC.

#### Setting Ethernet

Further information is available under 4.3.3. Ethernet communication.

#### 4.4.5.6. Editing Main Menu Analysis


You can test the functionality of analog and relay outputs. In addition, you can read off the minimum and maximum values (since the last voltage supply or reset of the min./max. values).

#### Testing functionality of analog outputs

- This function affects the analog outputs directly, not only the test contacts.
- In the Measuring Mode press SET, select main menu Analysis with ▶ or ▲ and confirm selection with SET.
- Test Analog Output is shown.
- Press SET and choose between Analog output 1, 2, 3 with ▶ or ▲.
- 3. Press SET, scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Any analog output value can be predefined, e.g. for an analog output of 4 to 20 mA, the value "6.0 mA". Confirm with SET or abort entry with ESC.

4. Accept setting by pressing SET and test with multimeter (minimum requirement: resolution 6.5 digits, at least 2-times more accurate than the 6383) as follows:

Analog output 1, 2 or 3: Via test contacts under service cover, see diagram.



 Return to Test Analog Output with ESC and use ➤ or ▲ to continue to Test Relay Output.

# Testing functionality of the pressure sensor (Test pressure sensor)



This function is only required to calibrate the pressure sensor.

#### Testing functionality of relay outputs

- 1. Press SET and choose between Alarm 1, 2, 3, 4 with ▶ or ▲.
- 2. Press SET.

The relay can now be tested. You can choose between OFF and ON using ▶ or ▲. If ON is chosen, the NO contact is closed, the NC contact opened. If OFF is chosen, the NC contact is closed, the NO contact opened.

- To test, route a measuring cable from the relay terminals (see 4.3.2.3. Connecting the relay outputs) out of the transmitter to a multimeter (resistance measurement) or continuity tester.
- Return to Test Relay Output with SET (starts relay test) or ESC (exits the menu without relay test).

#### Reading off min./max. values of channels

To reset the max./min. values, see 4.4.5.10. Editing Reset main menu.

- Read off the min./max. values of the three channels in succession with ▶ or ▲ and return to the Main Menu Analysis with ESC.
- Continue to Main Menu Message with ▶ or ▲ or return to Measuring Mode with ESC.

#### 4.4.5.7. Editing Message main menu

Messages can be confirmed/acknowledged, the last messages can be called up and the display of the messages can be switched on or off.




- 1 Operating hours at the time of message
- 2 Message code (see 4.5. Status, warning and error messages).
  - 3 Message text
  - 4 Message number (example: "4/7" refers to the fourth of seven messages)
    - 5 Number of messages present (example: "4/7" refers to the fourth of seven messages)
- Using the P2A software (see 7. volume 2, Parameterizing, adjusting and analyzing software (P2A software)) you can predefine whether messages are to be shown in the display.
- In the Measuring Mode press SET, select Main Menu Message with ▶ or ▲ and confirm selection with SET.
- 2. Confirm Confirm message using SET.
- 3. Select Last messages with ▶ or ▲ and confirm with SET.
- Scroll between the warning and error messages recorded so far using ▶ or ▲ and return to Last messages using ESC.
- 5. Select Information with ▶ or ▲ and confirm with SET.
- 7. Continue to Display of message with ▶ or ▲.

ON: Measurements are shown on the display in Measuring Mode.

OFF: No messages shown on display.

- 8. Select ON or OFF with ▶ or ▲ and confirm selection with SET.
- 9. Return to Main Menu Message with ESC.
- Continue to Main Menu Ident with ▶ or ▲ or return to Measuring Mode with ESC.
- An overview of the messages can be found in 4.5. Status, warning and error messages.

#### 4.4.5.8. Calling up Main Menu Ident



The serial numbers of the transmitter and probe can be read off.

- In the Measuring Mode press SET, select Main Menu Ident with ▶ or ▲ and confirm selection with SET.
- The type, firmware version, build number and serial number of the transmitter are displayed.
- This information is required when servicing.
- Return to Main Menu Ident with ESC or read off the type, firmware release, build number and serial number of the probe with ▶ or ▲ and then return to Main Menu Ident with ▶ or ▲.
- Continue to Main Menu Adjust with ▶ or ▲ or return to Measuring Mode with ESC.

#### 4.4.5.9. Editing Main Menu Adjust

A reference value can be entered for both relative humidity (RH) and temperature (°C/°F) for the 1-point adjustment. Please refer to

the description in 4.3.3.7. 1-point adjustment (offset - humidity/temperature).

The 2-point adjustment for the adjustment points 11.3 %RH/75.3 %RH and 20 %RH/80 %RH is carried out via operation menu.

Reference values for pressure can be entered for the n-point adjustment. Please refer to the description in 4.3.3.10. n-point adjustment (pressure).

In addition, the analog outputs can be adjusted. For instructions on how to do this. Also pay attention to 4.3.3.9. Analog output adjustment.

#### Enter reference value for 1-point adjustment

Please also refer to 4.3.3.7. 1-point adjustment (offset - humidity/temperature).

- In the Measuring Mode press SET, select main menu Adjust with ▶ or ▲ and confirm selection with SET.
- Reference value % RH is displayed.
- Press SET, edit value: Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.
- 3. Continue to Reference value temp with ▶ or ▲.
- Press SET, Reference value °C or Reference value °F is displayed.
- Press SET, edit value: Scroll one digit to the right using ▶ and increase value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.
- Continue to Analog Adj. Ch. 1 with ▶ or ▲.
- Continue with the adjustment of the analog outputs (see below, step 2) or press ESC to return to main menu Adjust.
- Continue to main menu Reset with ▶ or ▲ or return to Measuring Mode with ESC.

#### Carrying out a 2-point adjustment

- In measurement mode, press SET, select Main Menu Adjust with ▶ or ▲ and confirm selection with SET.
- Continue to 2 point adj 11/75% or 2 point adj 20/80% with ► or ▲.
- Press SET.
- 4. Continue to Adjust Point 11%/Adjust Point 20% or Adjust Point 75%/Adjust Point 80% with ▶ or ▲.
- 5. Confirm query with SET.
- In the display, 2 point adj 11/75% or 2 point adj 20/80%, 1-point adjustment, Probe reset appear one after the other.

After a probe reset, the adapted values appear.

#### Start self-adjustment

- The menu item self-adjustment is only visible when a testo 6615 probe is connected.
- In the Measuring Mode press SET, select Main Menu Adjust with ▶ or ▲ and confirm selection with SET.
- Select Self-adjust with ▶ or ▲ and confirm with SET.
- 3. Select Start Self-adjust with ▶ or ▲ and confirm with SET.
- Self-adjustment starts, the display value and the output value are "frozen".
- Continue to Cycle time with ► or ▲ (see below, step 2) or press ESC to return to Main Menu Adjust.

#### Setting cycle time of the self-adjustment

The time span to the next self-adjustment is shown in the status line of the display approx. every 5 seconds.

- In the Measuring Mode press SET, select Main Menu Adjust with ▶ or ▲ and confirm selection with SET.
- Select Self-adjust with ▶ or ▲ and confirm with SET.
- 3. Select Cycle time with ▶ or ▲ and confirm with SET.
- Select the desired value (48h / 24 h / 12 h / 6 h / 1 h / off) with
   or ▲, confirm with SET and return to Cycle time.
- Continue to Error signal on/off with ▶ or ▲ (see below, step 3) or press ESC to return to Main Menu Adjust.

#### Performing analog adjustment

- In the Measuring Mode press SET, select main menu Adjust with ▶ or ▲ and confirm selection with SET.
- Each channel is adjusted at three points in the analog range (at 10 %; 50 %; 90°% of the analog scale).
- 2. Select Analog Adj. Ch. 1 with ▶ or ▲ and confirm with SET.
- 3. Use ▶ or ▲ to select Adj. Point 1.
- Press SET. Read off multimeter display (e.g. 5601 mA) and enter this value in the user menu. Do this by scrolling one digit to the right using ▶ and increasing the value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.
- 5. Use ▶ or ▲ to select Adj. Point 2.
- Press SET. Read off multimeter display (e.g. 12,001 mA) and enter this value in the user menu. Do this by scrolling one digit to the right using ▶ and increasing the value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.

- 7. Use ▶ or ▲ to select Adj. Point 3.
- Press SET. Read off multimeter display (e.g. 18,401 mA) and enter this value in the user menu. Do this by scrolling one digit to the right using ▲ and increasing the value of digit by 1 using ▶. Confirm with SET or abort entry with ESC.
- With ▶ or ▲ continue to Analog Adj. Ch. 2or 3 (repeat steps 3 to 8).
- 10. Return to main menu Adjust with ESC.
- Continue to main menu Reset with ▶ or ▲ or return to Measuring Mode with ESC.

#### Performing the pressure adjustment

Please refer to 4.3.3.10. n-point adjustment (pressure)

- In the Measuring Mode press SET, select main menu Adjust with ▶ or ▲ and confirm selection with SET.
- The pressure adjustment can be performed at 3 to 6 adjustment points.
- Select Adjust Pressure with ▶ or ▲ and confirm with SET.
- 3. Use ▶ or ▲ to select Adj. Point 1.
- Press SET. Read off pressure sensor display (e.g. 30.1 Pa) and enter this value in the user menu. Do this by scrolling one digit to the right using ► and increasing the value of digit by 1 using ▲. Confirm with SET or abort entry with ESC.
- 5. Repeat steps 1 to 4 for adjustment points 2 to 6.
- 6. Return to main menu Adjust with ESC.
- Continue to main menu Reset with ▶ or ▲ or return to Measuring Mode with ESC.

#### 4.4.5.10. Editing Reset main menu

You can reset the factory settings for the following:

- Instrument
- Sensor/probe
- · Min./max. values
- Resetting to the factory settings means resetting to the order specification, i.e. the specific condition at the time of supply to the customer.
- In the Measuring Mode press SET, select Main Menu Reset with ▶ or ▲ and confirm selection with SET.
- Reset Device to factory settings is displayed.
- Select the setting to be reset using ▶ or ▲ and confirm selection with SET.

- Reset Completed is displayed.
- Return to the reset setting with ESC or SET and return to Main Menu Reset with ESC.
- Continue to Main Menu Channel 1 with ▶ or ▲ or return to Measuring Mode with ESC.

# 4.5. Status, warning and error messages

To achieve optimum operational reliability (machine availability), the transmitter shows the following via the user menu or the P2A software

- Status messages
- Warning messages
- Error messages

The status and warning messages for the respective testo 6610 probes connected to the transmitter can be evaluated via the P2A software.

All messages are stored in the transmitter with an operating hours stamp. Use the user menu (see 4.4.5.7. Editing Message main menu) or the P2A software (see 7.3.5. volume 2, Transmitter history) to view the message history.

In the transmitter, the last 60 status messages and the last 120 error and warning messages are stored in a ring memory. There is no limit in the P2A software.

## 4.5.1. Status messages

Status messages show the current operating status of the testo 6383.

Message	Display	Description
02506	Sensor initialization	Message appears while the transmitter is starting up. If the message disappears, the transmitter is ready for operation.
01D19	Service plug	The Mini-DIN socket is connected to: the USB adapter for P2A software, the adjustment adapter or the service plug (is not recorded/no number)
00300	New limit value	The limit value has been changed or shifted
00301	Scaling changed	The scaling has been changed

Message	Display	Description	
00500	Transmitter reset	The transmitter was reset to the factory settings and is restarted.	
0052F	Reset Min/Max	Resets all saved Min/Max values for all channels	
02518	Probe reset	Probe reset: The probe performs a reset	
00503	Reset device to fact	A factory reset of the transmitter was performed	
02503	Reset probe to fact	A factory reset of the probe was performed	
00530	Change solenoid valve	The solenoid valve should be changed	
00307	User Setting Change	User Setting Change: General settings were changed for the transmitter.	
00117	Adjustment DeltaP	An n-point adjustment was performed.	
02104	Analog adjustment	nt An analog adjustment has been made	
02101	1-point adjustment	A 1-point adjustment is performed.	
02102	2-point adjustment 11.3 %	As part of the 2-point adjustment, an adjustment is performed at 11.3 % RH	
02103	2-point adjustment 75.3 %	As part of the 2-point adjustment, an adjustment is performed at 75.3 % RH	
02120	2-point adjustment 20 %	As part of the 2-point adjustment, an adjustment is performed at 20 % RH	
02130	2-point adjustment 80 %	As part of the 2-point adjustment, an adjustment is performed at 80 % RH	
02105	Self-adjustment active	For testo 6615 probe only: The probe performs an automatic self-adjustment	

# 4.5.2. Warning messages

Warning messages show an early warning or a current malfunction which may negatively impact measuring.

Message	Display	Cause	Remedying of fault
00809	Pressure too high**	The process pressure exceeds the pressure intended for the transmitter	Remove the transmitter from the process and take any necessary measures to lower the pressure
00E00	T ambient high**	The ambient temperature exceeds the permissible temperature for the transmitter	Take necessary measures to lower ambient temperature, e.g. through venting or cooling
00E01	T ambient low**	The ambient temperature is below the permissible temperature for the transmitter	Take necessary measures to raise ambient temperature, e.g. through heating
00E04/00E 05	Supply voltage low**	The supply voltage is below the minimum voltage required for the transmitter	Take measures to ensure sufficient voltage supply
02822	T process high**	The process temperature exceeds the temperature designated for the probe	Remove the probe from the process and take any necessary measures to lower the process temperature
02821	T process low**	The process temperature is below the temperature designated for the probe	Take necessary measures to raise process temperature
0081C	Alarm 1**	Depending on the parameterization of the relays	Depending on the parameterization of the relays
0081D	Alarm 2**	Depending on the parameterization of the relays	Depending on the parameterization of the relays

Message	Display	Cause	Remedying of fault
0081E	Alarm 3**	Depending on the parameterization of the relays	Depending on the parameterization of the relays
0081F	Alarm 4**	Depending on the parameterization of the relays	Depending on the parameterization of the relays
02900	2-point adjustment drift*	In the 2-point adjustment, corrections repeatedly occur in the same direction; this may indicate a sensor drift	Send the probe into Testo Service
02806	Condensation*	100 % RH has been reached, condensation developing	Take measures to reduce process humidity
02807	Values less than 0 % RH**	The adjustment or sensor is faulty	Check adjustment (via P2A adjustment history, perform 2-point adjustment where necessary). If the problem persists, contact Testo Service
02809	Sensor early warning*	For testo 6617 probe only: The cover electrode of the sensor is damaged; this may soon cause the sensor to break	Carry out visual inspection. If the mirror-like surface of the sensor is dirty or damaged, contact Testo Service

<sup>\*</sup> Early warning

<sup>\*\*</sup> Current malfunction

# 4.5.3. Transmitter error messages

Error messages show a current malfunction.

Message	Display	Cause	Remedying of fault
03401	No probe signal	The probe communication is interrupted	Ensure that the probe connector is fully engaged in the transmitter.  If communication still cannot be established, contact Testo Service
03508	Wrong probe	The connected probe is not compatible with the present transmitter	Use a compatible probe Note: Probe 661x for transmitter 638x
01505	Watchdog error	Due to a processor error, the transmitter performs an automatic restart	If the problem occurs frequently, contact Testo Service
0300A	% RH short- circuit	Short-circuit in humidity sensor	Contact Testo Service
0300B	% RH sensor broken	The humidity sensor is damaged (sensor broken)	Contact Testo Service
0300C	T short-circuit	Short-circuit in temperature sensor	Contact Testo Service
0300D	T sensor broken	The temperature sensor is damaged (sensor broken)	Contact Testo Service
03105	Self-adjustment error	For testo 6615 probe only: The automatic self-adjustment was faulty	Contact Testo Service
03106	Adjustment error	The adjustment of the probe was faulty	Contact Testo Service
01115	Low adjustment temperature	The ambient temperature is too low during the pressure adjustment	Take necessary measures to raise ambient temperature, e.g. through heating

Message	Display	Cause	Remedying of fault
01116	High adjustment temperature	The ambient temperature is too high during the pressure adjustment	Take necessary measures to lower ambient temperature, e.g. through venting.
03000	Heat function defective	For testo 6614 probe only: Heat function defective	Contact Testo Service

# 4.5.4. Handling alarm messages

Shown on the display <sup>5</sup>	Can be used for collective alarm <sup>6</sup>	Additional message end <sup>7</sup>
New limit value	х	
Scaling changed	х	
Pressure too high	х	х
Delta p adjustment	х	
Alarm 1		х
Alarm 2		х
Alarm 3		Х
Alarm 4		Х
Transmitter reset	X	
Reset Min/Max		
Transmitter refresh	х	
User Setting Change		
Analog adjustment	х	
1-point adjustment	х	

<sup>&</sup>lt;sup>5</sup> If multiple messages/alarms are activated at the same time, only the last message/alarm is shown. If this is cancelled, the other messages that are still active are no longer displayed.

<sup>&</sup>lt;sup>6</sup> The message can be assigned the collective alarm function, which means that the collective alarm is activated as soon as at least one of the messages assigned to it is activated. The collective alarm can be assigned to each of the 4 optional relays. The collective alarm is then always the same, as it can only be defined once.

 $<sup>^7</sup>$  The message is shown upon the occurrence of the event causing the message as well as when closing. Two entries appear in the history in the P2A software: Message text\_start and Message text\_end.

Shown on the display <sup>5</sup>	Can be used for collective alarm <sup>6</sup>	Additional message end <sup>7</sup>
2-point adjustment 11.3%	х	
2-point adjustment 75.3 %	х	
Probe reset	х	
2-point adjustment drift	х	
T ambient high	х	Х
T ambient low	х	Х
Supply voltage low	х	х
T process high	х	х
T process low	х	х
Condensation	х	х
Values less than 0 % RH	х	х
Sensor early warning	х	
No probe signal	х	
Watchdog error	х	
% RH short-circuit	х	х
% RH sensor broken	х	х
T short-circuit	х	х
T sensor broken	х	х
Heat function defective	х	х

Perform the Confirm message function (acknowledgement of the alarm via the control keys on the transmitter):

- The message/alarm is no longer shown on the display and the optical alarm goes out, where applicable. If multiple messages/alarms are active at the same time, all are reset simultaneously.
- If at least one message is assigned to the collective alarm, the collective alarm is reset. If the collective alarm is set on a relay, the relay is also reset, meaning switched to its neutral position.

# 4.5.5. Namur fault conditions

If the faults named in the following table occur, the analog outputs output special values that enable a general fault warning in the higher-level control system. The values correspond to the "Namur" industry standard.

Status message in the display	Display value in display	Class	Analog output				
			0 to 20 mA	4 to 20 mA	1 V	5 V	10 V
No probe signal	None	Error	21 mA	21 mA	1.1 V	5.5 V	11 V
Wrong probe	None	Error	21 mA	21 mA	1.1 V	5.5 V	11 V
Values < 0 %RH	uuuuu	Underrange	0 mA	3.8 mA	0 V	0 V	0 V
Condensation	00000	Overrange	20.5 mA	20.5 mA	1.1 V	5.5 V	11 V
% RH short- circuit		Error	21 mA	21 mA	1.1 V	5.5 V	11 V
% RH sensor broken		Error	21 mA	21 mA	1.1 V	5.5 V	11 V
T short-circuit		Error	21 mA	21 mA	1.1 V	5.5 V	11 V
T sensor broken		Error	21 mA	21 mA	1.1 V	5.5 V	11 V
T process low	uuuuu	Underrange	0 mA	3.8 mA	0 V	0 V	0 V
T process high	00000	Overrange	20.5 mA	20.5 mA	1.1 V	5.5 V	11 V
Probe disconnected	None	Error	21 mA	3.8 mA	1.1 V	5.5 V	11 V
Watchdog error	Previous value stops	Error	21 mA	3.8 mA	1.1 V	5.5 V	11 V
Value below min. scale	Reading	Underrange	0 mA	3.8 mA	0 V	0 V	0 V

Status message in the display	Display value in display	Class	Analog output				
Value above max. scale	Reading	Overrange	20.5 mA	20.5 mA	1.1 V	5.5 V	11 V
Pressure too high	00000	Overrange	20.5 mA	20.5 mA	1.1 V	5.5 V	11 V
Heat function defective		Error	21 mA	21 mA	1.1 V	5.5 V	11 V

# 4.6. Maintenance and cleaning

# 4.6.1. Maintaining the instrument

We recommend that the adjustment and settings of the transmitter be checked at regular intervals using the


- User menu (4.4. Operation) or
- P2A software (7. volume 2, Parameterizing, adjusting and analyzing software (P2A software))

Convenient "remote monitoring" of the transmitter can be implemented, for example by using a relay as a collective alarm (see Using alarm as collective alarm or not using it at all, page 57) whose messages are forwarded to a local alarm transmitter (horn, light) or PLC.

# 4.6.2. Cleaning the instrument

# Integrated humidity probe

The humidity sensor of the integrated humidity probe in particular must be protected.



- 1. Put supplied plastic cap on the integrated humidity probe.
- Wipe surface of the instrument with mild cleaning agents and a soft cloth.
- 3. Remove plastic cap.

#### Instrument surface

- ✓ Integrated humidity probe is protected by the plastic cap.
- Clean the surface of the instrument with mild cleaning agents (e.g. washing-up liquid) and water. Only use gentle and standard cleaners.
- Do not use any aggressive or chafing cleaning agents such as thinner, liquid scouring agent, wax, benzine, concentrated acids and lyes.
- Carefully rub down the instrument surface with a moist and soft cloth.






# testo 6383 Ethernet· differential pressure transmitter

# testo 6610 · Probes

# P2A software · Parameterizing, adjusting and analyzing software

Instruction manual Volume 2





# 5 Contents

test	661	0 probes	8
6.1.	Spec	cifications	8
	6.1.1.	Functions and use	8
		6.1.1.1. Digital probes:	8
		6.1.1.2. The Testo humidity sensor	8
		6.1.1.3. Self-diagnosis	8
	6.1.2.	Design of the probe	8
	6.1.3.	Accessories	8
6.2.	Proc	luct description	8
	6.2.1.	Overview of probe and filter types	8
		6.2.1.1. Probe version	8
		6.2.1.2. Determining the accuracy/measuring uncertainty	8
		6.2.1.3. Ordering options for testo 6610 probe (0555 6610)	8
		6.2.1.4. Protection caps	8
	6.2.2.	Integrated humidity probe	8
	6.2.3.	testo 6613 cable probe	9
	6.2.4.	testo 6614 heated cable probe	9
	6.2.5.	testo 6615 trace humidity cable probe (self-adjustment)	9
	6.2.6.	testo 6617 cable probe (self-monitoring)	10
		6.2.6.1. Self-monitoring of cover electrode	10
6.3.	Com	missioning	10
	6.3.1.	Installing the probe	10
		6.3.1.1. Installing testo 6613/6614/6615/6617 probes	10
	6.3.2.	Connecting/removing the probe to/from the transmitter	11
6.4.	Maiı	ntenance and cleaning	11
	6.4.1.	Replacing filters/protection caps	11
		6.4.1.1. Replacing the filter/protection caps for wall version	11
		6.4.1.2. Replacing the filter/protection cap for duct versions	11
	6.4.2.	Cleaning the instrument and filter/protection cap	11
	6.4.3.	Replacing the sensor	11

	7.1.	Spec	cificatio	ons	114
		7.1.1.	Function	s and use	114
		7.1.2.	System re	equirements	115
		7.1.3.	Scope of	delivery	115
	7.2.	First	steps		115
		7.2.1.	Installing	the software/driver	115
			-	Installing P2A software	
			7.2.1.2.	Installing USB driver	116
			7.2.1.3.	P2A software upgrade	116
		7.2.2.	Starting t	the software	116
			7.2.2.1.	Starting the program	116
			7.2.2.2.	Establishing a connection with the instrument	116
			7.2.2.3.	Activating the connection with the instrument	117
	7.3.	Usin	g the s	software	117
		7.3.1.	User inte	rface	117
		7.3.2.	Editing in	strument/parameter file	120
			7.3.2.1.	Changing instrument/parameter file	120
			7.3.2.2.	Saving parameters	129
			7.3.2.3.	Opening the parameter file	130
			7.3.2.4.	Copying and pasting parameters	130
			7.3.2.5.	Deleting instrument/parameter file	131
			7.3.2.6.	Creating a new instrument file	131
		7.3.3.	Analyzing	g/testing the transmitter	131
			7.3.3.1.	Analyzing/testing the instrument	131
			7.3.3.2.	Carrying out factory reset	132
			7.3.3.3.	Testing analog output	132
			7.3.3.4.	Testing switch output relays 1 to 4	134
			7.3.3.5.	Displaying min./max. values	135
		7.3.4.	Adjusting	g the transmitter	136
			7.3.4.1.	1-point adjustment	
			7.3.4.2.	2-point adjustment	
			7.3.4.3.	n-point adjustment	
			7.3.4.4.	Adjusting the analog output	
		7.3.5.	Transmit	ter history	141
8	Tips	and a	assista	nce	146
	8.1.	Que	stions	and answers	146
	8.2.	Acce	essorie	es and spare parts	146
		8.2.1.	Ordering	options for testo 6383 transmitter (0555 6383)	148
		8.2.2.	Ordering	options for testo 6610 probes (0555 6610)	152

# 6 testo 6610 probes

# 6.1. Specifications

#### 6.1.1. Functions and use

The plug-in, adjusted probes from the testo 6610 family are used together with the testo 6383 transmitter.

These measuring units are suitable for the following applications, for example:

- Process instrumentation
- Clean rooms
- Test benches
- Drying processes
- Production and storage air quality
- Complex room climate applications.

## 6.1.1.1. Digital probes:

The probes are adjusted in the factory and transmit their adjustment data to the internal memory of the testo 6383 transmitter. The information is only transmitted between the probes and transmitter digitally. The probes can therefore be disconnected from the transmitter for adjustment or servicing while the transmitter itself can remain at the measuring point.



Hint: We recommend in this case that a probe of the same type be inserted into the transmitter immediately in order to be able to continue measuring with minimal interruption.

The transmitter identifies the probe and records that a probe was connected in the history.




The testo 6383 transmitter can only be used with testo 6610 probes.

# 6.1.1.2. The Testo humidity sensor

With the Testo humidity sensor, which has been in successful use and continually improved for more than ten years, the focus has from the very beginning been on both accuracy parameters, namely measuring uncertainty and long-term stability.

The capacitive humidity sensor is in principle a plate capacitor consisting of two electrically conductive plates (electrodes (1) and (2), see diagram below) opposite each other.

A humidity-sensitive polymer **(5)** serves as the dielectric. The special feature lies in the perfect way the individual layers are matched to each other. This is evident particularly in the top electrode, which has to perform two tasks that, at first glance, appear contradictory: it must be completely permeable to the water vapour that is to be fed into the polymer dielectric, but at the same time it must be impervious, smooth and repellent to condensate, oil and dirt in order to protect the sensor.



- Cover electrode
- 2 Bottom electrode
- Substrate (ceramic substrate for mechanical protection)
- 4 Connections (protected against corrosion)
- 5 Dielectric layer



The humidity sensor cannot be exchanged by the customer (except for 6611). The humidity sensor may not be damaged or touched. Contamination and damage lead to an impairment of the measurement and the measuring accuracy.

# 6.1.1.3. Self-diagnosis

The probes in the testo 6610 range monitor their functionality themselves and report the following faults:

- · Sensor breaks
- Sensor short-circuit
- Condensation


The condensation message is issued at a reading of 100 % RH and deactivated once the readings are within the valid range.

- Error message with drift at the adjustment points
- Value for relative humidity less than 0 % RH.
   The trigger threshold is set at -2 % RH. This means that an error message is only issued once a clear effect is discernible.
- Early warning when sensor corrosion is starting to develop
  The testo 6617 probe is able to signal the first signs of
  corrosion. The probe can thus be changed at an early stage
  without interrupting the machine availability.
- Self-adjustment (testo 6615 only)
- Excess temperature
   Error message if permissible process temperature is exceeded

# 6.1.2. Design of the probe

The probes of the testo 6610 family are made up of the following components (included in delivery):

- Probe connector
- Probe shaft with protection cap and sensors (% RH and °C or °F)
- Probe cable bend radius minimum Ø 50 mm.



- 1 Probe connector
- 2 Probe length
- 3 Probe
- 4 Protection cap, sensor underneath
- 5 Probe

# 6.1.3. Accessories

The following accessories are available for the probes from the testo 6610 family:

- Filters and protection caps (see 6.2.1.4. Overview of probe and filter types).
- Calibration certificate in accordance with ISO and DAkkS (see 8.2. Accessories and spare parts).

# 6.2. Product description

# 6.2.1. Overview of probe and filter types

#### 6.2.1.1. Probe version

A detailed description of the probe versions can be found from see 6.2.2. Integrated humidity probe, onwards.

The following probe versions are available for the testo 6383 transmitter:

Version	Article no.	Characteristic
Integrated humidity probe	KMAT option D04 (0636 6610)	<b>Wall</b> probe version; accuracy to ±1 % RH; temperature range -20 to +70 °C/-4 to +158 °F, plug-on sensor
testo 6612	0555 6610-L12	<b>Duct</b> probe version; accuracy to ±1 % RH; temperature range -30 to +150 °C/ -22 to +302 °F, sensor soldered
testo 6613	0555 6610-L13	Cable probe version; accuracy to ±1 % RH; temperature range -70 +180 °C / -94+356 °F, sensor soldered
testo 6614	0555 6610-L14	Heated cable probe version; accuracy to ±1 % RH; temperature range -40 to +180 °C/ -40 to 356 °F, sensor soldered
testo 6615	0555 6610-L15	<b>Trace humidity cable</b> probe version; accuracy to ±6 K at -60 °Ctd; temperature range -40 to +120 °C/-40 to +248 °F, sensor soldered
testo 6617	0555 6610-L17	Cable with cover electrode monitoring probe version; accuracy to ±1.2 % RH; temperature range -40 to +180 °C/ -40 to +356 °F, sensor soldered

# 6.2.1.2. Determining the accuracy/measuring uncertainty

The entries for the measuring uncertainty for the probe are determined in accordance with GUM (Guide to the Expression of Uncertainty in Measurement/DIN V ENV 13005).

All parts that make up the measuring uncertainty given by Testo are listed below. When comparing the measuring uncertainty/accuracy between manufacturers, which components are included is to be taken into account. In many cases, not all elements that contribute to measuring uncertainty are assessed, for

example if the error contribution of the production adjustment for some manufacturers is shown separately or not at all.

The measuring uncertainty of the probe includes the sensor and its electronics as well as the output of the digital measuring signal:

1	Linearity including scatter	Systematic error and scattering of the
		components (due to manufacturing

tolerances)

2 Hysteresis Hysteresis indicates the maximum deviation

> of the readings that are obtained when you set the same value for the parameter, once coming from a smaller value, once coming from a larger value (humidity sensors actually have no hysteresis, but rather very slow adjustment effects that appear to be hysteresis when considered only for a short

period.)

3 Reproducibility Repeatability (scattering of the readings in

the event of the same parameter being

entered successively)

4 Production adjustment area The measuring uncertainty of the reference

> instruments of the adjustment area (including the reference instrument) in production

Uncertainty of the procedure for determining 5 Uncertainty of the testing

points 1 and 2

#### 6.2.1.3. Ordering options for testo 6610 probe (0555 6610)

Order code	Characteristic
Lxx Probe type	
L12	Probe 6612
L13	Probe 6613
L14	Probe 6614
L15	Probe 6615
L17	Probe 6617
Mxx Protection caps	
M01	Protection cap made of stainless steel
M02	Protection cap made of wire mesh
M03	Protection cap made of PTFE

Order code	Characteristic
M04	Metal protection cap (open)
M06	PTFE protection cap with condensate drip hole
M07	Protection cap made of PTFE with condensate drip hole and condensation protector
M08	Protection cap for H <sub>2</sub> O <sub>2</sub> atmospheres
Nxx Cable length	
N01	1 m cable length (testo 6613, 6614, 6615, 6617)
N02	2 m cable length (testo 6613, 6614, 6615, 6617)
N05	5 m cable length (testo 6613, 6614, 6615, 6617)
N10	10 m cable length (testo 6613, 6614, 6615, 6617)
N23	Cable length specifically for duct versions (testo 6612)
Pxx Probe length	
P12	Probe length approx. 120 mm (testo 6613)
P20	Probe length approx. 200 mm (testo 6612, 6613, 6614, 6615, 6617)
P30	Probe length approx. 300 mm (testo 6612, 6613)
P50	Probe length approx. 500 mm (testo 6612, 6613, 6614, 6615, 6617)
P80	Probe length approx. 800 mm (testo 6612, 6613)

# 6.2.1.4. Protection caps

One of the following protection caps can be used for each probe version:


Filter*	Article no. **	Characteristic	Length A (mm)
M01	0554 0647	Protection cap made of stainless steel	33
M02	0554 0757	Protection cap made of wire mesh	40.3
M03	0554 0759	Protection cap made of PTFE	35
M04	0554 0755	Metal protection cap (open)	35
M06	0554 9913	PTFE protection cap with condensate drip hole	35
M07	0554 9913 +	Protection cap made of PTFE with	35
	0554 0166	condensate drip hole and condensation protector	55
M08	0699 5867/1	Protection cap for H <sub>2</sub> O <sub>2</sub> atmospheres	35

<sup>\*</sup> When ordering the probe, please use this protection cap code, cf. see 8.2.2. Ordering options for testo 6610 probes (0555 6610).

# 6.2.2. Integrated humidity probe

The integrated humidity probe is mounted on the wall together with the ready-wired testo 6383 transmitter.

#### At a glance



- 1 Protection cap
- 2 Probe shaft
- 3 Key
- 4 Connector

<sup>\*\*</sup> When purchasing a replacement (protection cap only), please use this order number.

#### **Application**

Monitoring and regulating the air quality in clean rooms



#### **Technical data**

#### **Parameters**

- Humidity (% RH/°Ctd/°Ftd) etc.
- Temperature

# Measuring range

Humidity: 0 to 100 % RH

Temperature: -20 to +70 °C/-4 to +158 °F

#### Material

• Probe shaft: Stainless steel

· Connector: ABS plastic

#### Accuracy (at 25 °C/77 °F)\*

· Humidity

• ±1.0 % RH / drift per year

- ± (1.0 % RH + 0.007 x reading) for 0 to 90 % RH
- ± (1.4 % RH + 0.007 x reading) for 90 to 100 % RH
- 0.02 % RH/K, dependent upon the process temperature (with a deviation of 25 °C/+77 °F)
- 0.02 % RH/K, dependent upon the electronics temperature (with a deviation of 25 °C/+77 °F)
- Temperature
  - ±0.15 °C (0.27 °F) with slope PT1000 class AA
  - \* Refer to the charts below for the correlation between temperature and accuracy.

#### Reproducibility

Better than ±0.2 % RH

#### Sensor


Response time without protective filter: t 90 max. 15 s

#### **Probe dimensions**


- · Diameter of probe shaft: 12 mm
- L = approx. 47 mm
- L A = 32 mm
- A = approx. 32 mm

#### Measuring accuracy of the integrated humidity probe

Humidity error, absolute  $|\pm\%$  RH| as a factor of process humidity (% RH)



Temperature error as a factor of process temperature and temperature of electronics




Grey line: System error 6383 + probe, electronics 25 °C/+77 °F Black line: System error 6383 + probe, electronics -25 to 70 °C/-13 to 158 °F

#### 6.2.3. testo 6613 cable probe

At a glance

The testo 6613 probe is used when the spatial separation of the transmitter and probe is required.



- Connector
- 3 Probe cable
- 4 Probe shaft
- 5 Protection cap (including: humidity and temperature sensor)

# **WARNING**


In the event of overpressures, the probe may become a projectile.

Mount the probe pressure-tight (see pressure resistance under Technical data)

# **Application**

- Monitoring and regulating industrial humidity processes (apart from high-humidity processes), e.g. food production, storing fruit
- Monitoring the production and storage air quality when manufacturing and storing hygroscopic products

- · Meeting the top accuracy requirements
- · Clean room applications
- · Applications for which a sturdy metal housing is required.
- Testo recommends that the testo 6614 (heated) probe be used for continuous high-humidity processes.



#### **Technical data**

#### **Parameters**

- Humidity
- Temperature

#### Measuring range

• Humidity: 0 to 100 % RH8

 $<sup>^8</sup>$  For constant use in high humidity (> 80% rF at ≤ 30°C for > 12 h, > 60% rF at > 30°C for > 12 h), please contact us via www.testo.com/service-contact

Temperature: -70 to +180 °C/-94 to +356 °F

#### Material

- Probe shaft: Stainless steel
- Line: Sheathed, FEP
- · Connector: ABS plastic

#### Accuracy (at 25 °C/77 °F)\*

- Humidity
  - ±1.0 % RH / drift per year
  - ± (1.0 % RH + 0.007 x reading) for 0 to 90 % RH
  - ± (1.4 % RH + 0.007 x reading) for 90 to 100 % RH
  - 0.02 % RH/K, dependent upon the process temperature (with a deviation of 25 °C/+77 °F)
  - 0.02 % RH/K, dependent upon the electronics temperature (with a deviation of 25 °C/+77 °F)
- Temperature
  - ±0.15 °C (0.27 °F) with slope PT1000 class AA
  - \* Refer to the charts below for the correlation between temperature and accuracy.

#### Reproducibility

Better than ±0.2 % RH

#### Sensor

Response time without protective filter: t 90 max. 15 sec.

#### **Probe dimensions**

- Diameter of probe shaft: 12 mm
- L = approx. 120/200/300/500/800 mm
- L A = 85/165/265/465/765 mm
- A, see 6.2.1.4. Overview of probe and filter types.

#### Probe length incl. probe shaft and filter


1/2/5/10 m

#### Pressure resistance\*\*


- PN 10 (probe tip)
- PN 1 (if end of probe/cable is involved in process)
- \*\* If installing probe under pressure, please use cutting ring screw connection (order no. 0554 1795).

#### Measuring accuracy of testo 6613 cable probe

Humidity error, absolute  $|\pm\%$  RH| as a factor of process humidity (% RH)



Temperature error as a factor of process temperature and temperature of electronics



Grey line: System error 6383 + probe, electronics 25 °C/+77 °F

Black line: System error 6383 + probe, electronics -25 to 70 °C/-13 to 158° F


# 6.2.4. testo 6614 heated cable probe

The testo 6614 heatable probe is suitable for use in high-humidity processes in which there is the possibility of condensation for the probe.

i

Also see 4.3.3.11. volume 1, High-humidity adjustment for testo 6614 for the functional principle of the testo 6614.

#### At a glance



- 1 Connector
- 2 Key
- 3 Probe cable
- 4 Probe shaft
- Filter (including: humidity and temperature sensor)
- 6 Temperature probe
- 7 Cable for temperature probe
- 8 Condensation protector (0554 0166)


# **A** WARNING

In the event of overpressures, the probe may become a projectile.

Mount the probe pressure-tight (see pressure resistance under Technical data)

#### **Application**

- Monitoring and regulating high-humidity processes, e.g. drying (ceramics, tobacco, wood, food) and maturing (cheese, fruit).
- At flow velocities > 1 m/s, an additional measuring uncertainty, not higher than +1.5 % RH, is to be expected. To prevent this error and ensure the highest measuring accuracy: Use condensation protector 0554 0166.



#### **Technical data**

#### **Parameters**

- Humidity
- · Temperature

#### Measuring range

- Humidity: 0 to 100 % RH
- Temperature: -40 to + 180 °C/-40 to 356 °F

#### Material

- Probe shaft: Stainless steel
- Line: Sheathed, FEP
- · Connector: ABS plastic

#### Accuracy (at 25 °C/77 °F)\*

- Humidity (values valid when using condensation protector 0554 0166)
  - ±1.0 % RH / drift per year
  - ± (1.0 % RH + 0.007 x reading) for 0 to 100 % RH
  - 0.02 % RH/K, dependent upon the process temperature (with a deviation of 25 °C/+77 °F)
  - 0.02 % RH/K, dependent upon the electronics temperature (with a deviation of 25 °C/+77 °F)
- Temperature
  - ±0.15 °C (0.27 °F) with slope PT1000 class AA
  - \* Refer to the charts below for the correlation between temperature and accuracy.

#### Reproducibility

± 0.2 % RH better

#### Sensor

Response time without protective filter: t 90 max. 15 sec.

#### Probe dimensions

- Diameter of probe shaft: 12 mm
- Diameter of temp. probe: 3 mm
- L = approx. 200/500 mm
- L A = 165/465 mm
- A see 6.2.1.4. Overview of probe and filter types.

#### Probe length incl. probe shaft and filter


1/2/5/10 m

#### Pressure resistance\*\*


- PN 10 (probe tip)
- PN 1 (if end of probe/cable is involved in process)
- \*\* If installing probe under pressure, please use cutting ring screw connection (order no. 0554 1795).

#### Measuring accuracy of heated testo 6614 cable probe

Humidity error, absolute |±% RH| as a factor of process humidity (% RH)



Temperature error as a factor of process temperature and temperature of electronics



Grey line: System error 6383 + probe, electronics 25 °C/+77 °F Black line: System error 6383 + probe, electronics –25 to 70 °C/-13 to 158° F

# 6.2.5. testo 6615 trace humidity cable probe (self-adjustment)


The testo 6615 probe corrects deviations in measurements by means of self-adjustment. This has a particular significance with low humidity values (in dewpoint range).

 $\mathbf{i}$ 

Also see 4.3.3.12. volume 1, **Self adjustment of testo 6615 trace humidity probe**, for the functional principle of the testo 6615.

Only use testo 6615 with sintered PTFE protection cap (art. no. 0554 0759) or sintered stainless steel protection cap (art. no. 0554 0647).

During the self-adjustment phase the signal values of the analog outputs remain on hold, meaning they are frozen for the duration.






#### **M** WARNING

In the event of overpressures, the probe may become a projectile.

Mount the probe pressure-tight (see pressure resistance under Technical data)

#### **Application**

- Monitoring and regulating trace humidity processes (compressed air with adsorption or membrane driers and plastic granulate driers)
- Used when spatial separation of transmitter and probe is required.



## **Technical data Parameters**

- Dewpoint
- Temperature

#### Measuring range

- Dewpoint: -40 to + 30 °Ctd/-148 to +212 °Ftd
- Temperature: -40 to ±120 °C/-40 to +248 °F
- (Temp. durability up to +180 °C/+356 °F)

#### Material

- Probe shaft: Stainless steel
- · Line: Sheathed, FEP
- Connector: ABS plastic

#### Accuracy (at 25 °C/77 °F)\*

- Humidity
  - ∘ ±1.0 % RH / drift per year
- Dewpoint
  - ± 1 K at 0 °Ctd/+32 °Ftd
  - ± 2 K at -40 °Ctd/-40 °Ftd
  - ± 4 K at -50 °Ctd/-58 °Ftd
  - ± 6 K at -60 °Ctd/-76 °Ftd
- Dependent on the process temperature (deviation of 25 °C / 77 °F)
  - ± 0.1 Ktd/K at -40 °C to 25 °C/-40 °F to +77 °F
  - ± 0.2 Ktd/K at 25 °C to 50 °C/77 °F to 122 °F
  - ± 0.4 Ktd/K at 50 °C to 120 °C/122 °F to 248 °F
- Temperature
  - ±0.15 °C (0.27 °F), slope PT1000 class AA
  - \* Refer to the charts below for the correlation between temperature and accuracy.

#### Sensor

• Response time without protective filter: t 90 max. 15 sec.

#### **Probe dimensions**

- · Diameter of probe shaft: 12 mm
- L = approx. 200/500 mm
- L A = 165/465 mm
- A see 6.2.1.4. Overview of probe and filter types.


#### Cable length incl. probe shaft and filter

• 1/2/5/10 m


#### Pressure resistance

- PN 16 (probe tip)\*\*
- \*\* If installing probe under pressure, please use cutting ring screw connection (order no. 0554 1795).

# Measuring accuracy of testo 6615 trace humidity cable probe Dewpoint error, absolute $|\pm\%$ RH| as a factor of process dewpoint (°Ctd)



# Temperature error as a factor of process temperature and temperature of electronics




Grey line: System error 6383 + probe, electronics 25 °C/+77 °F Black line: System error 6383 + probe, electronics -25 to 70 °C/-13 to 158° F

# 6.2.6. testo 6617 cable probe (self-monitoring)

The testo 6617 probe is used if spatial separation of the transmitter and probe is required, particularly for media (gases, vapours) which can jeopardize/damage the humidity sensor (the testo 6617 has a self-monitoring and early-warning function for such applications).







In the event of overpressures, the probe may become a projectile.

Mount the probe pressure-tight (see pressure resistance under Technical data)


#### **Application**

- Monitoring and regulating industrial humidity processes involving corrosive media (apart from high-humidity processes) with the exception of applications with HCL, HF and other acids and acidifiers in larger concentrations (SO<sub>2</sub>, SO<sub>3</sub>, NO<sub>2</sub>)
- · Meeting the top accuracy requirements
- Applications for which a sturdy metal housing is required
- This probe does NOT have a longer life with exposure to aggressive media than the testo 6613, for example. However, early warning of damage to the sensor is given so that machine failures can be avoided.

# 6.2.6.1. Self-monitoring of cover electrode

Use in harsh ambient conditions with aggressive media in some cases incurs the risk of damage to the sensor.

Damage to the sensor is generally reflected by incorrect readings which occur a long time before the sensor is wrecked. If this damage to the sensor is not spotted until too late, high costs can be incurred due to unusable readings or machine shutdowns and waiting times until the sensor is replaced.




- 1 Cover electrode
- 2 Bottom electrode
- 3 Substrate (ceramic substrate for mechanical protection)
- 4 Connections (protected against corrosion)
- 5 Dielectric layer

The testo 6617 has a unique self-monitoring function.

This allows early detection of damage to the sensor, e.g.:

- Mechanical damage (e.g. scratches)
- Damage from aggressive gases (e.g. acids in aerosol form)
- Swelling or detachment of polymer layer due to effects of solvents

Once the self-monitoring reaches the specific limit value, the probe warning message "Sensor early warning" is issued.



#### **Technical data**

#### **Parameters**

- Humidity (% RH/°Ctd/°Ftd)
- Temperature

# Measuring range

Humidity: 0 to 100 % RH<sup>9</sup>

Temperature: -40 to +180 °C/-40 to 356 °F

#### Material

Probe shaft: Stainless steel

Line: Sheathed, FEP

· Connector: ABS plastic

<sup>9</sup> For constant use in high humidity (> 80% rF at  $\le$  30°C for > 12 h, > 60% rF at > 30°C for > 12 h), please contact us via www.testo.com/service-contact

#### Accuracy (at 25 °C/77 °F)\*

- Humidity
  - ±1.0 % RH / drift per year
  - ± (1.2 % RH + 0.007 x reading) for 0 to 90 % RH
  - ± (1.6 % RH + 0.007 x reading) for 90 to 100 % RH
  - 0.02 % RH/K, dependent upon the process temperature (with a deviation of 25 °C/+77 °F)
  - 0.02 % RH/K, dependent upon the electronics temperature (with a deviation of 25 °C/+77 °F)
- Temperature
  - ±0.15 °C (0.27 °F) with slope PT1000 class AA
  - \* Refer to the charts below for the correlation between temperature and accuracy.

#### Reproducibility

Better than ±0.2 % RH

#### Sensor

Response time without protective filter: t 90 max. 15 sec.

#### Probe dimensions

- Diameter of probe shaft: 12 mm
- L = approx. 200/500 mm
- L A = 165/465 mm
- A see 6.2.1.4. Overview of probe and filter types.

#### Probe length incl. probe shaft and filter


1/2/5/10 m

#### Pressure resistance


- PN 10 (probe tip)\*\*
- \*\* If installing probe under pressure, please use cutting ring screw connection (order no. 0554 1795).

# Measuring accuracy of testo 6617 cable probe (self-monitoring)

Humidity error, absolute |±% RH| as a factor of process humidity (% RH)



Temperature error as a factor of process temperature and temperature of electronics



Grey line: System error 6383 + probe, electronics 25 °C/+77 °F Black line: System error 6383 + probe, electronics –25 to 70 °C/-13 to 158° F

# 6.3. Commissioning

# 6.3.1. Installing the probe


# 6.3.1.1. Installing testo 6613/6614/6615/6617 probes

If used with these probes, the testo 6383 transmitter is mounted on the wall, see 4.3. volume 1, Commissioning.

Install probe according to the application and the measuring and spatial conditions, cf. cases A1 to C below

In processes with which condensate forms at the humidity probe, install the probe vertically (filter points downwards).


## A 1 Wall mounting of probe



1 Wall/duct holder (order no. 0554 6651)

# A 2 Wall mounting of testo 6614 heated probe


When mounting the testo 6614 heated probe version, the temperature probe must be secured as close to the humidity probe as possible (max. 10 cm). An appropriate assembly tool is supplied with the testo 6614.




- 1 Wall/duct holder (order no. 0554 6651)
- 2 testo 6614
- 3 Distance of probe tips of humidity probe temperature probe: As close as possible, but without touching (distance between probe tips max. 10 cm)
- 4 Assembly tool, supplied with the wall/duct holder (order no. 0554 6651)
- 5 Temperature probe

#### B Duct mounting of testo 6614 heated probe

When mounting the testo 6614 heated probe version, the temperature probe must also secured at a distance of approximately 10 cm from the humidity probe. An appropriate assembly tool is supplied with the testo 6614.



- 1 Wall/duct holder (order no. 0554 6651)
- 2 testo 6614
- 3 Temperature probe
- 4 Assembly tool, supplied with the wall/duct holder (order no. 0554 6651)
- 5 Direction of flow
- 6 approx. 10 cm distance



1 Cutting ring screw connection (order no. 0554 1795)

During installation, ensure that the probe cannot be damaged during operation.

 $\mathbf{i}$ 

For the testo 6614 (heated probe version), please use the cutting ring screw connection, order no. 0400 6193, to assemble the temperature probe.

## 6.3.2. Connecting/removing the probe to/from the transmitter

- Insert probe connector into socket of testo 6383 until it engages. The testo 6383 identifies which probe is connected.
- To remove the probe, the lock release button on the probe must be pressed so that this can be removed.

### 6.4. Maintenance and cleaning

### 6.4.1. Replacing filters/protection caps

### 6.4.1.1. Replacing the filter/protection caps for wall version




- Do not damage the sensors when exchanging the filter/the protection cap and do not touch their surfaces!
- 1. Unscrew defective filter/protection cap (2) from probe shaft (1).
- 2. Screw new filter/protection cap onto probe shaft.
- Screw on protection cap by hand, i.e. do not tighten it using a tool.

#### 6.4.1.2. Replacing the filter/protection cap for duct versions

i

The following descriptions applies to these probes:

- testo 6613
- testo 6614
- testo 6615
- testo 6617



- Do not damage the sensor when exchanging the filter/the protection cap and do not touch its surface!
- 1. Unscrew defective filter/protection cap (2) from probe shaft (1).
- 2. Screw new filter/protection cap onto probe shaft.
- Screw on protection cap by hand, i.e. do not tighten it using a tool.

### 6.4.2. Cleaning the instrument and filter/protection cap

- Only clean the instrument carefully with a moist cloth.
- Do not use aggressive cleaning agents.
- Do not use any solvents.
- Unscrew cap or protection cap to clean, clean with compressed air and replace. Take care not to damage the sensor!

### 6.4.3. Replacing the sensor

Thanks to the probe concept (digital, plug-in), all probes can be changed in situ within seconds if necessary, generally without any interruption to the operation of the machine.



To maintain the extremely high accuracy of the testo 6610 probe, it is not possible for customers to change the sensor. Please contact your Testo Service team for this.

# 7 Parameterizing, adjusting and analyzing software (P2A software)

### 7.1. Specifications

The P2A software is used for the parameterizing, adjustment and analysis of testo transmitters. The following applies:

- Generally, all newer testo transmitters (as of 2007) are supported.
- For each newly purchased Testo transmitter, a free software upgrade must be installed, containing the instrument drivers for all transmitters which are connectable at that time.
- This upgrade can be downloaded free of charge at any time from the Testo homepage www.testo.com/download-center (requires registration).

The software must only be bought one time, even for owners of several testo transmitters.

#### 7.1.1. Functions and use

In the P2A software, two different file types are used: The instrument and the parameter file.

#### Instrument file

The parameters of a particular transmitter are stored in its so-called instrument file. Using this file, the parameters can be edited and the instrument can be tested and adjusted.

Instrument files also contain the respective histories in addition to the parameter data, i.e. "log books" are kept for the previous parameterizations, adjustments and messages (see 7.3.5. Transmitter history).



Instrument files are ".cfm" format files.

#### Parameter file

Parameter files are not tied to a specific individual transmitter and contain only parameter data/no history data.

If you use various instruments of the same type, you can create parameter files once (e.g. by saving the appropriate instrument file as the parameter file) and transmit these onto the other instruments.



Parameter files are ".cfp" format files.

#### 7.1.2. System requirements

#### Operating system

- Windows® 7
- Windows<sup>®</sup> 8
- Windows® 10

#### Computer

The computer must fulfil the requirements of the respective operating system. The following requirements must additionally be fulfilled:

- Interface USB 1.1 or higher
- Graphic resolution min. 1024 x 768



Date and time settings are automatically taken over from the computer. The administrator must ensure that the system time is regularly synchronized with a reliable time source, in order to guarantee the authenticity of the data.

#### Software

The P2A software must be purchased and installed separately from the transmitter. If it is a new software version, the transmitter is already supported completely. Older P2A software versions can be updated via the P2A software upgrade.

### 7.1.3. Scope of delivery

Included in the scope of delivery are:

- P2A software
- USB driver



When working with the parameterizing, adjusting and analyzing software (P2A software), previous knowledge of Windows® operating systems is assumed.

### 7.2. First steps

### 7.2.1. Installing the software/driver



Adminstrator rights are required for installation.

#### 7.2.1.1. Installing P2A software



Without the input of a licence key, the software will run only as a demo version (time limit 30 days).

- You can download the software under the following link: <a href="https://www.testo.com/download-center">https://www.testo.com/download-center</a>. If the installation program does not start automatically: > Open download folder and start P2A.exe.
- 2. Follow the instructions of the installation wizard.
- 3. Click on [Finish] to complete the software installation.

#### 7.2.1.2. Installing USB driver

- You can download the USB driver under the following link: <a href="https://www.testo.com/download-center">https://www.testo.com/download-center</a> (Testo USB driver) If the installation program does not start automatically: > Open download folder and start USBDriver.exe.
- 2. Follow the instructions of the installation wizard.
- 3. Click on [Finish] to complete the software installation.

#### 7.2.1.3. P2A software upgrade

- Download and store P2A software upgrade from www.testo.com/download-center (requires registration).
- 2. Select folder into which the downloaded Zip file was stored, and unzip the file.
- 3. Start file P2A upgrade.exe.
- 4. Follow instructions from installation assistant.

#### 7.2.2. Starting the software

#### 7.2.2.1. Starting the program

> Click on All Programs (Windows® 7, Windows® 8, Windows® 10) | Testo | P2A- Software.



In Windows® 7 the window User account control is opened when starting the software the first time.

- > Click on Accept.
- The program window is opened (see 7.3. User interface).

#### 7.2.2.2. Establishing a connection with the instrument



The instrument works with limited functionality, if it is only supplied via the service plug. Some settings, which can be parameterized in the P2A software, will only be executed by the instrument, after it has been connected to the

electric power supply.

Multiple instruments can be attached, however only one connection is active at all times.

- √ USB driver is installed (see 7.2.1.2. Installing USB driver).
- 1. Start the P2A software.
- Connect adapter (supplied with the P2A software) to the service interface of the instrument (see 4.2.4. volume 1, Service interface).
- 3. Connect instrument/adapter to the PC via the USB interface.
- The instrument file of the attached instrument is shown in the file list


#### 7.2.2.3. Activating the connection with the instrument

- > Click on the desired instrument file.
- The selected file is marked in colour and the connection with the instrument is activated.

If a connection with the instrument is established when the program is started, the corresponding instrument file is marked automatically.

### 7.3. Using the software

### 7.3.1. User interface



#### 1 Menu bar:

Menu	Command	Explanation
File	Open	Shows the Windows dialogue for searching and opening files.
	Save as	Saves the parameters of an instrument or parameter file under a new name.
Edit	Сору	Copies the parameters of the marked instrument or parameter file in the cache.
	Paste	Pastes the parameters from the cache in the marked instrument or parameter file.
View	Toolbar Status bar	Activates/deactivates the toolbar or status bar.
?	Check instrument connections	Checks the connections to a connected instrument without the instrument having to be activated.
	Service	A text file with the most important information on the computer and the software is opened via Display service data.
	Information	Shows the version number of the P2A software.

2 Toolbar: Shows the Windows-compliant icons for editing.

#### 3 File:

Icon	File	Explanation
Symbol shows a	Instrument file	Instrument file Connection to the instrument has
transmitter		been established.
		<type> <serial number="">.cfm</serial></type>
		File name should not be changed.

Icon	File	Explanation
Symbol shows a transmitter with a red minus sign in the upper left corner	Instrument file	Instrument file Connection to the instrument has not been established.
Symbol shows a transmitter with a white P for parameter file in the upper left corner	Parameter file	<type> <serial number=""> <date> <time>.cfp  File name can be changed.  The name can be selected freely, but it is recommended that you retain the reference to the instrument.  Parameter files are always marked red; the parameter values they contain are only forwarded to the instrument after being transmitted to the instrument file.</time></date></serial></type>

4 Function buttons: Dialogues on editing and testing the instrument are opened by means of the buttons.

[Change parameterization] see 7.3.2.1. Changing instrument/parameter file.

[Test/analyze transmitter] see 7.3.3. Chapter Analyzing/testing the transmitter.

[Adjusting the transmitter] see 7.3.4. Chapter Adjusting the transmitter.

[Transmitter history] see 7.3.5. Transmitter history.

#### 5 File information:

Status	Shown in the window
An instrument file is selected	Type, serial number, firmware version of the instrument.
A parameter file is selected	Type, serial number and firmware version of instrument for which the parameter file was created.
Connection status	Green = connection is active Red = connection is inactive

6 Status bar: Shows the current status when editing via the menu bar.

### 7.3.2. Editing instrument/parameter file


#### 7.3.2.1. Changing instrument/parameter file

- The desired instrument/parameter file is marked.
- 1. Click on [Change parameterization].
- The Properties of <Instrument type> <Serial number>
  dialogue is opened with the Change parameterization register.

If the parameters were transmitted from other parameter files into the instrument file, a message is shown with which you can transmit the new parameters to the connected instrument using [Yes].

- > If the parameters should not be transmitted, click on [No].
- 2. Change or enter parameters in the corresponding fields.

Field	Explanation
Unit/	All analog outputs are parameterized in this
Analog output	mask.




Field	Explanation
Unit/analog output (graphic)	Unit: 0 to 1 V/5 V/10 V or 0 to 20 mA/4 to 20 mA.
	Vertical: Current version of the analog output (cannot be changed).
	Horizontal: Min./max. scale end points of selected unit.
	The curve changes in accordance with the entered value of scale minimum and maximum.
Scale minimum/ maximum	The endpoints of the scaling can be selected up to the stored scale minimum and maximum. In the process, scaling can take place beyond the measuring range in order to adjust the analog output to the customer system, see 4.2.8. volume 1, Scaling.
Unit	Selection of the physical unit.  When changing the unit, standard values are set for scale minimum and maximum.  Caution!
	When changing the phys. unit, the relay limit values are set to the assigned default values.
Signal delay (graphic)	Curve changes according to the set signal delay.
Signal delay	Time interval in stages 1 – 15: 1 = no delay 15 = longest delay.
	The signal delay is added to the reaction time of the sensor. The signal delay shows averaging over the time interval of the selected stage in seconds:
	Example Stage 10 = average of the readings from the last 10 seconds.

1	
_	

The delay of the signal in relation to the change in the process is also significantly influenced by the selection of the particle filter.


Field Explanation

Field	Explanation
	In this mask, the relays or display alarms are parameterized.



Relay x/alarm x	Four relays or alarm values are available (optional).
Not used	Relay is not used. Hysteresis image and input options are hidden.
Collective alarm	A relay can be used as a collective alarm detector in the event that selected messages appear. Selection of the messages (OR linkage) by selecting the checkbox.
Min control	If switched to ON (NO contact) or OFF (NC contact) under the limit value; in the event of a subsequent exceeding of Limit value plus Hysteresis, it is switched to OFF (NO contact) or ON (NC contact).

Field	Explanation
Max control	If switched to ON (NO contact) or OFF (NC contact) above the limit value; in the event of a subsequent undershooting of Limit value minus Hysteresis, it is switched to OFF (NO contact) or ON (NC contact).




The graphic display in the centre of the screen refers to the relay wiring as a NO contact (ON).

	· ,
Hysteresis	To avoid switching cycles.
Channel	Selection of the channel that is to be monitored.
Limit value	Values for the limits of the unit selected in Unit/analog output; 4 decimal places. When changing the phys. unit, the relay limit values are set to the default values.
Visual alarm display	Checkbox is activated: Upon the appearance of the selected alarm, the background lighting of the display and the corresponding measurement value flashes.

Field	Explanation
Alarm delay	The desired alarm delay for the alarms of the min/max control and the visual alarm is entered in the input field (0 to 3600 seconds possible).
	The alarm delay has no effect on the collective alarms.

Field	Explanation
-	Setting the absolute pressure and selection of the H <sub>2</sub> O <sub>2</sub> evaporation process for the parameter °C <sub>tm</sub> ).




Absolute pressure

The absolute pressure is included in the calculation of the following units:


- °CtdA or °FtdA
- g/kg or gr/lb
- · ppmV% vol.


Field	Explanation
H <sub>2</sub> O <sub>2</sub> process	<ul> <li>The calculation of the mixture dewpoint unit °C<sub>tm</sub> is dependent upon the type of the evaporation process:</li> <li>with passive vaporization: H<sub>2</sub>O<sub>2</sub> solution evaporates (with active vaporization)</li> <li>with active vaporization: H<sub>2</sub>O<sub>2</sub> solution is evaporated over a heated metal plate (with active vaporization)</li> <li>Input field: Entering the weight proportion of the liquid H<sub>2</sub>O<sub>2</sub> compared to water in %.</li> </ul>
Button	Explanation
Ethernet	Networking the transmitters via Ethernet. For a multitude of applications, measurement data can be simultaneously recorded, documented and visualized.




Start wizard...

Address allocation of the testo 6383 with Ethernet module:





Field	Explanation	
Valid password	Display of the current password.	
Field	Explanation	



i

The accuracy specifications are only valid for the zeroing cycle of 15 sec set by the factory.

Zeroing cycle setting Selection of the time interval after which the automatic zeroing cycle is to occur.

Recommendation: 15 sec

Field Explanation

Field		Explanation	
Self-adjustment Setting the self-adjustment.			
testo 6383 00456123 Properties			X
Alarm 3     Alarm 4     Basic settings     Proces pressure humidity     Display     Set-adjustment	witch:	the self-adjustment cycle time the analog outputs and the alarms are ad oit.  ivate self-adjustment for the testo 6615 probe  justment every:  Hour	testo 6383 SN 00456123 FW 1.00 testo 6611 PSN 01677791 Communication 0K
		OK	Cancel Apply
Activate self- adjustment for the testo 6615 probe		<ul> <li>Checkbox is activated: The adjustment is performed in</li> <li>Checkbox is not activated: adjustment is not performe</li> </ul>	the set cycle. The self-
Self-adjustment every		Setting the cycletime in which adjustment is to be performed	the self-
		In order to receive relia during the calibration of period of the probe, test recommends the short cycle time.  A longer cycle time car continuous operation.	r equalization sto est possible
[Start self adjustment]		Start self adjustment at a defir outside the cycle time.	ned time

#### 7.3.2.2. Saving parameters

Parameters can be saved in new parameter files.

- 1. Mark instrument/parameter file.
- 2. Click on File > Save as in the menu bar.

- 3. Select storage location and enter the file name.
- 4. Click on [Save].
- The new parameter file is shown in the file list.

Only the parameters are saved from an instrument file; the history data are not adopted.



The original name (Instrument type, Serial number) is suggested with the current date/time as standard, e.g. "testo 6383 01234578 061120 1403.cfp".

For a standard installation, the files are saved under "C:\Documents and Settings\All Users\Shared Documents\P2A Software". The path can differ depending on the version of the operating system.

#### 7.3.2.3. Opening the parameter file

All parameter files stored in the standard directory path are automatically displayed in the file list when the software is started. You can also open parameter files that are stored in other directories.

- 1. Click on File > Open in the menu bar.
- 2. Select the storage location and click on the requisite file.
- Click on [Open].
- The selected file is opened. This can be changed and saved (see 7.3.2. Editing instrument/parameter file).

### 7.3.2.4. Copying and pasting parameters

The parameters of a parameter file can be transmitted to an instrument file or another parameter file from the same instrument type.

- 1. Select file from which parameters are to be copied.
- 2. Click on Edit > Copy in the menu bar.
- 3. Select the file which is to be modified.
- Click on Edit > Paste in the menu bar.
- The parameters are transmitted to the file.



You can also use the common keyboard shortcuts for copying (CTRL+C) and pasting (CTRL+V).

Parameters can also be transmitted using drag & drop, where you drag the icon of the parameter file onto the icon of the target instrument file.

- 5. Connect and select corresponding instrument.
- 6. Click on [Change parameterization].
- 7. Confirm confirmation request.

Parameter data are transferred to the instrument.

#### 7.3.2.5. Deleting instrument/parameter file

Instrument/parameter files can be deleted from the file list.

- 1. Click on the file that is to be deleted with the right mouse button.
- 2. Select the command Delete in the context menu.
- The instrument or parameter file is deleted from the list.

#### 7.3.2.6. Creating a new instrument file

It is possible to create an instrument file without restarting the P2A software.

- √ Transmitter must be connected.
- 1. Click on File > New connection in the menu bar.
- Connection to the transmitter is established.

### 7.3.3. Analyzing/testing the transmitter

In this section, you can test the outputs of the connected instrument, read off the limit values and reset the parameters to the factory settings.

The function is only available for instrument files.

### 7.3.3.1. Analyzing/testing the instrument

- √ The required instrument file is marked.
- 1. Click on [Test/analyze transmitter].
- The Properties of <Instrument type> <Serial number>
  dialogue is opened with the Test/analyze transmitter register.
- 2. Perform action:

Action	Explanation
Carrying out factory reset	Reset the unit, limit value and hysteresis parameters to factory settings (see below).
Testing analog output	Test channel 1/optional 2/3 (see 7.3.3.3. Testing analog output).
Test switch outputs	Manually switch relays 1 to 4 to test for proper function (see 7.3.3.4. Testing switch output relays 1 to 4).
Display min./max. values	Overview of the minimum and maximum values measured since the last reset of the transmitter (see 7.3.3.5. Displaying min./max. values).

3. Click on [OK] or [Cancel] to close the dialogue.

#### 7.3.3.2. Carrying out factory reset


- √ The required instrument file is marked.
- 1. Click on [Test/analyze transmitter].
- The Properties of <Instrument type> <Serial number> dialogue is opened with the Test/analyze transmitter register.
- 2. Mark transmitter test.
- Current operating hours are shown.
- 3. Confirm control query to perform the reset.
- The values are reset to the customer-specific factory settings.
- 4. Click on [OK] or [Cancel] to close the dialogue.

#### 7.3.3.3. Testing analog output

- √ The required instrument file is marked.
- 1. Click on [Test/analyze transmitter].
- The Properties of <Instrument type> <Serial number> dialogue is opened with the Test/analyze transmitter register.

#### 2. Mark channel and test values.

Field/button	Explanation
	Check the analog outputs (see 4.4.5.6. volume 1, Editing Main Menu Analysis).




Current reading	Readings are updated every second.
Unit	Unit according to the type of analog output.
Default value	Freely definable output value for the respective type of analog output (V or mA), 1 decimal place.
[Activate]	The entered default value is forwarded to the corresponding analog output and to the test contacts by clicking.
	A warning informs that the value is being transmitted to the connected instrument in the event of existing cabling.
	Now check the analog output using a precise multimeter.
[Deactivate]	Finish entering the electrical variables at the analog output.  The analog output returns to the current reading again.

- 3. Click on [OK] or [Cancel] to close the dialogue.
- The analog output and the relay return to Measuring Mode again.

#### 7.3.3.4. Testing switch output relays 1 to 4

- √ The required instrument file is marked.
- 1. Click on [Test/analyze transmitter].
- The Properties of <Instrument type> <Serial number> dialogue is opened with the Test/analyze transmitter register.
- 2. Mark Relay tests and test the values.

Field/button	Explanation
	Test the relay function (see 4.4.5.6. volume 1, see Editing Main Menu Analysis).



[Activate relay n]	Close contact.  A warning informs that the value is being
	transmitted to a connected PLC, external display, etc. in the event of existing cabling.
[Deactivate relay n]	Open contact.  A warning informs that the value is being transmitted to a connected PLC, external display, etc. in the event of existing cabling.


- 3. Click on [OK] or [Cancel] to close the dialogue.
- The analog output returns to Measuring Mode again.

#### 7.3.3.5. Displaying min./max. values

The transmitter saves the minimum or maximum value for each channel (measured since the last voltage supply or since the last manual reset).

- √ The required instrument file is marked.
- 1. Click on [Test/analyze transmitter].
- The Properties of <Instrument type> <Serial number>
  dialogue is opened with the Test/analyze transmitter register.
- 2. Mark Min./max. values.

Field/button	Explanation
	View the min./max. values of each channel. Only the values within the measuring range are shown.



Channel	Min./max. of channel 1/2/3 (optional)
Value	Min. or max. value, 1 decimal place.
Unit	Unit selected in Unit/analog output.

- 3. Reset Min./max. values.
- 4. Click on [Reset min./max. values].

- 5. Confirm control query to perform the reset.
- The values are reset to the factory settings.
- 6. Click on [OK] or [Cancel] to close the dialogue.

### 7.3.4. Adjusting the transmitter

This function is used to adjust an attached instrument. The following adjustments may be carried out using the software:

- 1-point adjustment (offset)
- 2-point adjustment (upper and lower adjustment point)
- Analog adjustment (entry via assistant/wizard)
- n-point adjustment (entry via assistant/wizard)

Also see 4.3.3.5. volume 1, Adjusting the instrument.


#### 7.3.4.1. 1-point adjustment



The testo 400/650 with precision humidity probe (order no. 0636 9741) is recommended as the reference measuring instrument for 1-point adjustment (offset) (see 4.3.3.7. volume 1, Adjusting testo 6383 using testo handheld instrument).

- Expose the reference measuring instrument and the instrument to be adjusted to the same constant conditions and wait for equalization period to lapse.
- 2. Mark the instrument file of the connected instrument.
- 3. Click on [Adjusting the transmitter].
- The Properties of <Instrument type> <Serial number>
  dialogue is opened with the Adjusting the transmitter register.
- Enter reference value and click on [Carry out 1-point adjustment].

- 5. Confirm confirmation request.
- The adjustment is carried out.



- > Click on [Set offset to zero] to reset a transmitted reference value.
- The current reading is used again.
- 6. Click on [OK] or [Cancel] to close the dialogue.

#### 7.3.4.2. 2-point adjustment

Also see 4.3.3.8. volume 1, 2-point adjustment (humidity/temperature).

- Expose the reference measuring instrument and the instrument to be adjusted to the same constant conditions and wait for equalization period to lapse.
- 2. Mark the instrument file of the connected instrument.
- 3. Click on [Adjusting the transmitter].
- The Properties of <Instrument type> <Serial number>
  dialogue is opened with the Adjusting the transmitter register.
- 4. Mark 11.3 %, enter the reference value for the lower adjustment point and click on [Lower adjustment point].
- The adjustment is carried out.
- 5. Mark 75.3 %, enter the reference value for the upper adjustment point and click on [Upper adjustment point].
- The adjustment is carried out.


Field	Explanation
Current reading	Reading in % RH.
	Readings are updated every second.
Reference value	Entry of the read-off value from the reference measuring instrument.
	Permissible entries:
	Lower adjustment point 10.3 to 12.3 % RH
	• Upper adjustment point 74.3 to 76.3 % RH.

6. Click on [OK] or [Cancel] to close the dialogue.

#### 7.3.4.3. n-point adjustment

- Connect precision pressure sensor (see 4.3.3.10. volume 1, n-point adjustment (pressure)).
- 2. Mark the instrument file of the connected instrument.
- 3. Click on [Adjusting the transmitter].
- The Properties of <Instrument type> <Serial number>
  dialogue is opened with the Adjusting the transmitter register.
- 4. Mark n-point adjustment.

- Click on [Start wizard ...] and follow the instructions of the wizard.
- The adjustment is performed when the wizard is closed.



How much pressure Requi is actually applied the pr


Required field: Entry of the value read off at the pressure sensor.

- The n-point adjustment must always be carried out to its full extent and in good time at all selected adjustment points.
- The number of adjustment points (3 to 6) is stored in the user menu of the transmitter and can only be changed via the P2A software.

#### 7.3.4.4. Adjusting the analog output

- 1. Connect precision multimeter (see 4.3.3.9. volume 1, Analog output adjustment).
- 2. Mark the instrument file of the connected instrument.
- 3. Click on [Adjusting the transmitter].
- The Properties of <Instrument type> <Serial number>
  dialogue is opened with the Adjusting the transmitter register.

- Click on [Start wizard ...] and follow the instructions of the wizard.
- The adjustment is performed when the wizard is closed.



### 7.3.5. Transmitter history


Parameterizations, adjustment processes and messages that have occurred are registered in the transmitter with an operating hours stamp.

In the history overviews (explained later in more detail), past processes and events can be made visible.

For parameter changes or adjustments that are performed directly at the instrument (via the user menu), "Transmitter" is entered in the User field and only the operating hour is entered in the Date/time field instead of operating hour/date/time.

For entries that are performed using the P2A software, the name of the user logged into Windows appears in the User field, while the date/time and operating hour are shown in the Date/time field.


- 1. Mark the instrument file of the connected instrument.
- 2. Click on the [Transmitter history] button.
- The Properties of <Instrument type> <Serial number> dialogue is opened with the Transmitter history register.
- 3. Click on the required entry in the list to change the display.



Operating hours / date/time

Operating hour/time stamp at which the change at the instrument was performed.


Field	Explanation
User	Name with which the user is logged into the operating system.  "Transmitter" entry if the change was performed at the instrument.
Comments	Type of parameter change, e.g. "Unit of channel 1 from Pa to hPa".



Selection of adjustment histories: 1-point adjustments / 2-point adjustments / Analog adjustments / n-point adjustments.

Serial no. Probes	Serial number of the probe.
Probe operating hour	Operating hour of the probe at which the change at the instrument was performed.
User	Name with which the user is logged into the operating system.  "Transmitter" entry if the change was performed at the instrument.
Reference value	If no changes were performed, no value is displayed.
Unit	Unit during the adjustment.
Reading	1-point adjustment: If no changes were performed, no value is displayed.


Field	Explanation
Offset from	1-point adjustment: Value before the adjustment.
Offset to	1-point adjustment: Value after the adjustment.
Offset	2-point adjustment: Difference between target and actual value reported by instrument.
Pressure specification	n-point adjustment: Reference value set at the pressure sensor.
Channel	Analog adjustment: Channel 1 to n.
Specification	Analog adjustment: Actual value.
Multimeter	Analog adjustment: Reference value set at the multimeter.
Offset	Analog adjustment: Deviation at time of adjustment.



Selection of probe adjustment histories: 1-point adjustments / 2-point adjustments / Error/status messages.

Serial number of the transmitter to which the probe was connected at the time of the
adjustment.

Field	Explanation
Operating hour probe	Operating hour of the probe at which the change at the instrument was performed.
Unit	Unit during the adjustment.
Offset from	1-point adjustment: Value before the adjustment.
Offset to	1-point adjustment: Value after the adjustment.
Target value	2-point adjustment: Reference value.
Reading	2-point adjustment: Value before the adjustment.
Difference	2-point adjustment: Difference determined by instrument between target value and reading.
Error/status messages	Error/status messages: The error/status messages assigned to the probe.



The table is shown only for error and status messages that were generated in the transmitter and were transferred and saved there via the connection to the P2A software.

Operating hours	Operating hour at which the message appeared in the instrument.
Serial number	Serial number of the instrument to which the message is assigned

Field	Explanation
Message	e.g. "Scaling changed". The scaling was changed.
Type of message	e.g. early warning, status message.

- > To print out the history data, click on [Print].
- The printing job is automatically sent to the default printer for the operating system.

  With [Set up printer ...] a different printer can be selected or the printout can be edited.
- 4. Click on [OK] or [Cancel] to close the dialogue.

### 8 Tips and assistance

### 8.1. Questions and answers

Question	Possible causes/solution
Connection to instrument cannot be established	Check connection cable/plug contacts
A message appears on the display	See 4.5. volume 1, Status, warning and error messages
Malfunction (with and without display)	Analysis using the P2A software, see 7.3.3. Analyzing/testing the transmitter
When does a stable current reading appear?	After approx. 20 seconds

If we could not answer your question, please contact your dealer or Testo Customer Service. For contact details see the rear side of this document or the web page www.testo.com/service-contact

### 8.2. Accessories and spare parts



An overview of the probes that can be used with the testo 6383 can be found in volume 1, see 6.2.1. Overview of probe and filter types.

Description	Article no.
Spare parts	
Integrated humidity probe	0636 6610
Sealing frame	0554 6384
Protection Cap for the built-in humidity probe	0554 6385
Interface and software	
P2A software (parameterizing, adjusting, analyzing) incl. USB adapter	0554 6020
testo 400/650 adapter	0554 6022
<b>Dewpoint measurement</b> (only with testo 6615)	
Preliminary filter to protect measurement chamber and sensors against contamination	0554 3311
Precision chamber with adjustable inflow	0554 3312

Flow meter for measurement chamber for setting the specified inflow of the sensor	0554 3313
Cooling coil for process temperatures > 50 °C/122 °F (up to 200 °C/392 °F), only with precision measurement chamber	0554 3304
2 m PTFE tube with compressed air connections up to 140 °C/284 °F, max. 9000 hPa, only with precision measurement chamber	0699 2824
Protection caps	
Protection cap made of stainless steel (for integrated probe 0636 6610)	0170 0263
Protection cap made of stainless steel	0554 0647
Woven wire filter protection cap	0554 0757
Protection cap made of PTFE	0554 0759
Metal protection cap (open)	0554 0755
PTFE protection cap with condensate drip hole	0554 9913
Protection cap made of PTFE with condensation protector and condensate drip hole	0554 0166
Protection cap for H <sub>2</sub> O <sub>2</sub> atmospheres	0699 5867/1
Hoses	
Silicone hose ID 4 transparent	0086 0001, sold by the metre
TYGON hose ID 4.8 transparent	0086 0031, sold by the metre
Silicone hose transparent, internal diameter 2 mm, for test pressure connections 6383	0086 0003, sold by the metre
Supply	
Mains unit (desktop, wall-mounted)	0554 1748
Mains unit (top-hat rail mounting)	0554 1749
Extension and calibration cable	0554 6610
External display	
Process display for testo 54-2 AC	5400 7553
Process display for testo 54-7 AC	5400 7555

Calibration	
Standard ISO calibration certificate, transmitter only	0520 1000
Standard DAkkS calibration certificate, transmitter only	0520 1200
Standard ISO calibration certificate, transmitter + probes	0520 0176
Special ISO calibration certificate, transmitter + probes	0520 0066
Standard DAkkS calibration certificate, transmitter + probes	0520 0276
Special DAkkS calibration certificate, transmitter + probes	0520 0236
ISO calibration certificate humidity, probes	0520 0076
DAkkS calibration certificate temperature, probes	0520 0261

For a complete list of all accessories and spare parts, please refer to the product catalogues and brochures or look up our website at: www.testo.com

# 8.2.1. Ordering options for testo 6383 transmitter (0555 6383)

Order code	Characteristic
Axx Measuring range	
A01	0 to 50 Pa
A02	0 to 50 Pa
A03	0 to 100 Pa
A04	0 to 500 Pa
A05	0 to 10 hPa
A21	-10 to 10 Pa
A22	-50 to 50 Pa
A23	-100 to 100 Pa
A24	-500 to 500 Pa
A25	-10 to 10 hPa

Order code	Characteristic
Bxx Analog output/supply	
B02	0 to 1 V (4-wire, 24 V AC/DC)
B03	0 to 5 V (4-wire, 24 V AC/DC)
B04	0 to 10 V (4-wire, 24 V AC/DC)
B05	0 to 20 mA (4-wire, 24 V AC/DC)
B06	4 to 20 mA (4-wire, 24 V AC/DC)
Cxx Display	
C00	Without display
C02	With display/English
C03	With display/German
C04	With display/French
C05	With display/Spanish
C06	With display/Italian
C07	With display/Japanese
C08	With display/Swedish
Dxx Integrated humidity probe	
D00	No humidity/temperature probe
D04	Humidity/temperature probe integrated in panel
D05	Preparation for external humidity/temperature probe testo 6610 probe
Exx Ethernet	
E00	Without Ethernet interface
E01	With Ethernet interface
Fxx Differential pressure unit <sup>10</sup>	
F01	Pa/Min/Max

 $<sup>^{10}</sup>$  Scaling +/- 50 % of measuring range possible

Order code	Characteristic
F02	hPa/Min/Max
F03	kPa/Min/Max
F04	mbar/Min/Max
F05	bar/Min/Max
F06	mmH <sub>2</sub> O /Min/Max
F07	inchH <sub>2</sub> O /Min/Max
F08	inch HG/Min/Max
F09	kg/cm² /Min/Max
F10	PSI/Min/Max
Gxx Optional analog output for humidity probe connection testo 6610/units <sup>11</sup>	
G01	% RH/Min/Max
G02	°C/Min/Max
G03	°F/Min/Max
G04	°Ctd/Min/Max
G05	°F <sub>td</sub> /Min/Max
G06	g/kg /Min/Max
G07	gr/lb /Min/Max
G08	g/m³ /Min/Max
G09	gr/ft³ /Min/Max
G10	ppmV/Min/Max
G11	°C <sub>wb</sub> /Min/Max
G12	°F <sub>wb</sub> /Min/Max
G13	kJ/kg /Min/Max (enthalpy)
G14	mbar/Min/Max (water vapour partial pressure)
G15	inch H <sub>2</sub> O/Min/Max (water vapour partial pressure)

.

 $<sup>^{11}</sup>$  Only if D04 or D05 is selected

Order code	Characteristic
G16	°C <sub>tm</sub> (dewpoint for H <sub>2</sub> 0 <sub>2</sub> mixture)
G17	°F <sub>tm</sub> (dewpoint for H <sub>2</sub> 0 <sub>2</sub> mixture)
G18	% vol
Hxx Relay	
H00	Without relay
H01	4 relay outputs, limit value monitoring
H02	4 relay outputs, channel 1 limit values and collective alarm
Ixx Units, channel 3 (only if optional humidity probe connection is available) <sup>12</sup>	
I01	% RH/Min/Max
102	°C/Min/Max
103	°F/Min/Max
104	°Ctd/Min/Max
105	°F <sub>td</sub> /Min/Max
106	g/kg /Min/Max
107	gr/lb /Min/Max
108	g/m³ /Min/Max
109	gr/ft³ /Min/Max
I10	ppmV/Min/Max
I11	°C <sub>wb</sub> /Min/Max
l12	°F <sub>wb</sub> /Min/Max
I13	kJ/kg /Min/Max (enthalpy)
114	mbar/Min/Max (water vapour partial pressure)
I15	inch H <sub>2</sub> O/Min/Max (water vapour partial pressure)

\_

 $<sup>^{12}\,</sup>$  Only if D04 or D05 is selected

Order code	Characteristic
I16	°C <sub>tm</sub> (dewpoint for H <sub>2</sub> 0 <sub>2</sub> mixture)
l17	°F <sub>tm</sub> (dewpoint for H <sub>2</sub> O <sub>2</sub> mixture)
I18	% vol
l19	%RH <sub>m</sub> (mixture humidityfor H <sub>2</sub> 0 <sub>2</sub> )

### 8.2.2. Ordering options for testo 6610 probes (0555 6610)

Order code	Characteristic
Lxx Probe type	
L12	Probe 6612
L13	Probe 6613
L14	Probe 6614
L15	Probe 6615
L17	Probe 6617
Mxx Protection caps	
M01	Protection cap made of stainless steel
M02	Protection cap made of wire mesh
M03	Protection cap made of PTFE
M04	Metal protection cap (open)
M06	PTFE protection cap with condensate drip hole
M07	Protection cap made of PTFE with condensate drip hole and condensation protector
M08	Protection cap for H <sub>2</sub> O <sub>2</sub> atmospheres
Nxx Cable length	
N02	1 m cable length (testo 6613, 6614, 6615, 6617)
N03	2 m cable length (testo 6613, 6614, 6615, 6617)
N04	5 m cable length (testo 6613, 6614, 6615, 6617)
N05	10 m cable length (testo 6613, 6614, 6615, 6617)

Order code	Characteristic
N06	Cable length specifically for duct versions (testo 6612)
Pxx Probe length	
P12	Probe length approx. 120 mm (testo 6613)
P20	Probe length approx. 200 mm (testo 6612, 6613, 6614, 6615, 6617)
P30	Probe length approx. 300 mm (testo 6612, 6613)
P50	Probe length approx. 500 mm (testo 6612, 6613, 6614, 6615, 6617)
P80	Probe length approx. 800 mm (testo 6612, 6613)



#### Testo SE & Co. KGaA

Celsiusstraße 2 79822 Titisee-Neustadt Germany

Telefon: +49 7653 681-0 E-Mail: info@testo.de Internet: www.testo.com