ID	Title	External_doc	External_risks	External_validation	External_validation_test
100208-5236	Anbindung 3G/4G Modem über Ethernetschnittstelle	Base Internal GSM modem (2G) might be replaced by external gateway with 3G/4G connection. 2G modem will be deactivated if external modem is selected. External modem supports SMS alarming in 3G/4G communication, but with restriced functionality.	- SMS size generally limited to max. 140 char (for internal modem too) - no supervision of SMS delivery possible	yes	Alarm functionality by SMS has to be checked if external modem is used instead of internal GSM module.
100208-5337	FW - Base hängt beim Herunterfahren "Shutdown - Loading CommUp"	Base V2 in some cases the Saveris Base was blocked during shutdown. The issue has been solved.	none		
100208-5061	Alarm - AM mismatch between colors and values in table and alarmlog	Ethernetprobe In some cases a mismatch between colours and values in table and alarmlog was observed. Also the behaviour between alarm by email and alarm by SMS was different. Now the behaviour is synchronized for email and SMS alarms - the corresponding colour fits to the listed start and end of alarm timepoints in both cases.	none		
100208-5169	Unnötiger Eintrag in der Konfigurationsvorgabe der Ethernet-Logger	Ethernetprobes In the config memory range of ethernetprobes a value was stored which is only in use for Radio	none		

		probes. This config-value for radio probes will not be stored to ethernetprobes furtheron.	
100208-5112	Alarm - Dauer Alarmverzögerung wird von Türkontakt-Messpunkten verkürzt	Radio probes V1 and V2 Alarm-delay is based on numbers of standard measuring cycles . If alarm delay is used in combination with door-contact, the alarm comes earlier than expexted because door-opening creates additional timestamps between the standard cycle timestamps and reduces the alarm-delay. Now this reduction is blocked.	none
100208-4749	Alarm - Neue Darstellung der Alarmnachrichten	The e-mail alarm message body has been re-formatted and enhanced. Here is a sample: TestoSaveris-Alarm 67373337-1 - //nnpce1610/tsaveris -------------------- AlarmID: 67373337 Condition: 18.2 °C < 20.0 °C Date Time: 19.09.2016 13:21:00 ------Source------- <devicename> SN: <serialnumber> Channel: <channelnumber> Zone(s): <Zone>[,morezones] Project: <projectname>	none

```
--------------------
<Alarm message text>
--------------------
```