



Bootloader Control Unite 350_v2010

firmware file:

Changes

Release version: V 1.04

V 1.07

There is a new Bootloader V 1.07 available for the CU and the MB. Firmware-Updates with CU and MB with Bootloader-Versions lower than V 1,07 can lead to problems in combination with windows 7, as the testo devices are not recognised as removable data carriers. Remedy would be to be connected the products by a USB hub with Windows to 7 computers. The problem is solved with new Bootloader.

How to update the bootloader:

The bootloader file needs to be updated in the same way as you update the firmware file. Please proceed the boot loader before you update the firmware file.
